OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
8426
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- LTR)

DIAGNOSIS

Recommendation
The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
Metal levels are typical for a new component breaking in.

Contamination
There is a moderate amount of fuel present in the oil. Test for glycol is negative. Tests confirm the presence of fuel in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0085668**	GFL0059840	GFL0059890
Sample Date		Client Info		**06 Nov 2023**	02 Mar 2023	16 Nov 2022
Machine Age	hrs	Client Info		**540**	0	0
Oil Age	hrs	Client Info		**540**	0	560
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**ABNORMAL**	SEVERE	ABNORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	**30**	28	38
Chromium	ppm	ASTM D5185(m)	>20	**1**	2	2
Nickel	ppm	ASTM D5185(m)	>4	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	<1	<1
Silver	ppm	ASTM D5185(m)	>3	**<1**	0	0
Aluminum	ppm	ASTM D5185(m)	>20	**2**	3	3
Lead	ppm	ASTM D5185(m)	>40	**3**	<1	<1
Copper	ppm	ASTM D5185(m)	>330	**133**	3	2
Tin	ppm	ASTM D5185(m)	>15	**0**	<1	<1
Antimony	ppm	ASTM D5185(m)		**0**	<1	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**20**	7	2
Barium	ppm	ASTM D5185(m)	0	**10**	0	0
Molybdenum	ppm	ASTM D5185(m)	60	**44**	50	62
Manganese	ppm	ASTM D5185(m)	0	**3**	<1	<1
Magnesium	ppm	ASTM D5185(m)	1010	**714**	791	807
Calcium	ppm	ASTM D5185(m)	1070	**1128**	957	1034
Phosphorus	ppm	ASTM D5185(m)	1150	**585**	877	844
Zinc	ppm	ASTM D5185(m)	1270	**776**	1012	1068
Sulfur	ppm	ASTM D5185(m)	2060	**1626**	2275	2376
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**17**	14	11
Sodium	ppm	ASTM D5185(m)		**13**	▲ 1780	▲ 903
Potassium	ppm	ASTM D5185(m)	>20	**5**	▲ 92	▲ 193
Fuel	%	ASTM D7593*	>5	▲ **6.3**	<1.0	<1.0
Glycol	%	ASTM D7922*		**0.0**	⬢ 0.538	▲ 0.035

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	**0.3**	0.3	0.5
Nitration	Abs/cm	ASTM D7624*	>20	**11.4**	19.3	15.0
Sulfation	Abs/.1mm	ASTM D7415*	>30	**21.7**	24.6	26.0

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**22.1**	21.6	23.6

OIL ANALYSIS REPORT

Glycol Contamination



▲ Viscosity @ 100°C



Glycol Contamination



VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	▲ .2%	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.4	▲ **13.0**	13.6	13.9

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



▲ Viscosity @ 100°C



▲ Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0085668
Lab Number : 02595277
Unique Number : 5672356
Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel)

Received : 09 Nov 2023
Diagnosed : 10 Nov 2023
Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 221 - Windsor
905 Tecumseh Road W
Windsor, ON
CA N8W 4J5
Contact: Rhys Marotte
rmarotte@gflenv.com
T:
F: