OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Area
GFL207
Machine Id
800025
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (20 LTR)

DIAGNOSIS

▲ Recommendation

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0102729**	GFL0094541	GFL0088994
Sample Date		Client Info		**31 Jan 2024**	17 Nov 2023	28 Aug 2023
Machine Age	hrs	Client Info		**13291**	16706	16132
Oil Age	hrs	Client Info		**0**	0	0
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**SEVERE**	ABNORMAL	ABNORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>75	**25**	28	29
Chromium	ppm	ASTM D5185(m)	>5	**<1**	<1	1
Nickel	ppm	ASTM D5185(m)	>4	**<1**	<1	0
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**0**	<1	0
Aluminum	ppm	ASTM D5185(m)	>15	**2**	3	3
Lead	ppm	ASTM D5185(m)	>25	**<1**	<1	0
Copper	ppm	ASTM D5185(m)	>100	**<1**	1	<1
Tin	ppm	ASTM D5185(m)	>4	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**1**	2	4
Barium	ppm	ASTM D5185(m)	0	**0**	0	0
Molybdenum	ppm	ASTM D5185(m)	60	**51**	51	54
Manganese	ppm	ASTM D5185(m)	0	**0**	0	<1
Magnesium	ppm	ASTM D5185(m)	1010	**842**	842	863
Calcium	ppm	ASTM D5185(m)	1070	**958**	939	923
Phosphorus	ppm	ASTM D5185(m)	1150	**876**	861	908
Zinc	ppm	ASTM D5185(m)	1270	**1047**	1058	1052
Sulfur	ppm	ASTM D5185(m)	2060	**2286**	2171	2243
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**5**	6	6
Sodium	ppm	ASTM D5185(m)		**7**	9	9
Potassium	ppm	ASTM D5185(m)	>20	**2**	3	3
Fuel	%	ASTM D7593*	>3.0	**▲ 7.6**	▲ 6.1	▲ 5.1

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	**0.8**	0.8	0.8
Nitration	Abs/cm	ASTM D7624*	>20	**12.2**	11.7	12.4
Sulfation	Abs/.1mm	ASTM D7415*	>30	**24.5**	26.1	27.8

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 100°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**25.0**	27.6	29.3

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.4	**12.9**	▲ 12.4	13.2

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0102729
Lab Number : 02613392
Unique Number : 5722487
Test Package : MOB 1 (Additional Tests: PercentFuel)

Received : 05 Feb 2024
Tested : 06 Feb 2024
Diagnosed : 27 Feb 2024 - Kevin Marson

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 207 - Pickering SW
1034 TOY AVENUE, PICKERING YARD
PICKERING, ON
CA L1W 3P1
Contact: Ian Patton
ipatton@gflenv.com
T: (905)831-6297
F: (905)426-3577