OIL ANALYSIS REPORT

Sample Rating Trend

FUEL

Machine Id
P231 25054
Component
Diesel Engine
Fluid
DIESEL ENGINE OIL SAE 15W40 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 15W40. Please confirm.

Wear

All component wear rates are normal.

Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.

Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PC0083814**	---	---
Sample Date		Client Info		**13 Jan 2024**	---	---
Machine Age	mths	Client Info		**0**	---	---
Oil Age	mths	Client Info		**6**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**MARGINAL**	---	---

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	---	---
Glycol		WC Method		**NEG**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>75	**33**	---	---
Chromium	ppm	ASTM D5185(m)	>5	**1**	---	---
Nickel	ppm	ASTM D5185(m)	>4	**<1**	---	---
Titanium	ppm	ASTM D5185(m)	>2	**0**	---	---
Silver	ppm	ASTM D5185(m)	>2	**0**	---	---
Aluminum	ppm	ASTM D5185(m)	>15	**3**	---	---
Lead	ppm	ASTM D5185(m)	>25	**2**	---	---
Copper	ppm	ASTM D5185(m)	>100	**5**	---	---
Tin	ppm	ASTM D5185(m)	>4	**<1**	---	---
Antimony	ppm	ASTM D5185(m)		**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	250	**<1**	---	---
Barium	ppm	ASTM D5185(m)	10	**0**	---	---
Molybdenum	ppm	ASTM D5185(m)	100	**61**	---	---
Manganese	ppm	ASTM D5185(m)		**0**	---	---
Magnesium	ppm	ASTM D5185(m)	450	**966**	---	---
Calcium	ppm	ASTM D5185(m)	3000	**1089**	---	---
Phosphorus	ppm	ASTM D5185(m)	1150	**1004**	---	---
Zinc	ppm	ASTM D5185(m)	1350	**1179**	---	---
Sulfur	ppm	ASTM D5185(m)	4250	**2587**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**7**	---	---
Sodium	ppm	ASTM D5185(m)	>158	**5**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**1**	---	---
Fuel	%	ASTM D7593*	>3.0	**2.1**	---	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	**2.2**	---	---
Nitration	Abs/cm	ASTM D7624*	>20	**14.0**	---	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	**30.9**	---	---

OIL ANALYSIS REPORT

Viscosity @ 40°C



Viscosity @ 100°C

Viscosity @ 40°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**29.1**	---	---

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	---	---
Free Water	scalar	Visual*		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	115	**113**	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	14.4	**14.9**	---	---
Viscosity Index (VI)	Scale	ASTM D2270*	126	**136**	---	---

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0083814 **Received** : 01 Mar 2024
Lab Number : 02619206 **Tested** : 06 Mar 2024
Unique Number : 5736316 **Diagnosed** : 06 Mar 2024 - Kevin Marson
Test Package : MOB 1 (Additional Tests: FUELDILUTION, KV40, PercentFuel, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

TORONTO FIRE SERVICES
40 TORYORK DRIVE
TORONTO, ON
CA M9L 1X6
Contact: Antonio Rodrigues
antonio.rodrigues@toronto.ca
T:
F: (416)338-9207