PROBLEM SUMMARY

Area
1311
Machine Id
ROCK BREAKER HYDRAULIC POWER UNIT
Component
Hydraulic Power Pack
Fluid
PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL (200 LTR)

Sample Rating Trend



ISO

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS

Sample Status				**SEVERE**	SEVERE	SEVERE
Particles >4µm		ASTM D7647	>5000	▲ **113295**	▲ 71134	▲ 63837
Particles >6µm		ASTM D7647	>1300	▲ **22125**	▲ 6966	▲ 6548
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **24/22/15**	▲ 23/20/13	▲ 23/20/15
White Metal	scalar	Visual*	NONE	▲ **VLITE**	NONE	▲ VLITE
PrtFilter					*no image*	

Customer Id: INCVOS
Sample No.: PC0070688
Lab Number: 02620857
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Resample	---	---	?	Resample in 30-45 days to monitor this situation.
Check Breathers	---	---	?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check For Visual Metal	---	---	?	We advise that you check for visible metal particles in the oil.
Check Seals	---	---	?	Check seals and/or filters for points of contaminant entry.

HISTORICAL DIAGNOSIS

ISO

29 Apr 2023 Diag: Wes Davis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report

VISUAL METAL

08 Feb 2023 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.Light concentration of visible metal present. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >6µm are abnormally high. Particles >6µm are abnormally high.. Particles >14µm are notably high. Light concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid.

view report

ISO

12 Jul 2022 Diag: Wes Davis

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >6µm are severely high. Particles >4µm are severely high. Oil Cleanliness are severely high. Particles >14µm are abnormally high. Particles >21µm are abnormally high. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report

OIL ANALYSIS REPORT

Area
1311
Machine Id
ROCK BREAKER HYDRAULIC POWER UNIT
Component
Hydraulic Power Pack
Fluid
PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL (200 LTR)

Sample Rating Trend



ISO

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. We advise that you check for visible metal particles in the oil. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

Light concentration of visible metal present.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Particle Filter (Magn: 200 x)



SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PC0070688**	PC0057680	PC0040345
Sample Date		Client Info		**27 Feb 2024**	29 Apr 2023	08 Feb 2023
Machine Age	yrs	Client Info		**0**	0	0
Oil Age	yrs	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**SEVERE**	SEVERE	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	**5**	6	7
Chromium	ppm	ASTM D5185(m)	>10	**0**	0	<1
Nickel	ppm	ASTM D5185(m)	>10	**<1**	0	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	<1
Silver	ppm	ASTM D5185(m)		**0**	0	0
Aluminum	ppm	ASTM D5185(m)	>10	**<1**	<1	1
Lead	ppm	ASTM D5185(m)	>10	**0**	<1	<1
Copper	ppm	ASTM D5185(m)	>75	**2**	3	3
Tin	ppm	ASTM D5185(m)	>10	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	<1	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	**0**	<1	<1
Barium	ppm	ASTM D5185(m)	0	**0**	0	0
Molybdenum	ppm	ASTM D5185(m)	0	**0**	0	0
Manganese	ppm	ASTM D5185(m)	1	**0**	0	0
Magnesium	ppm	ASTM D5185(m)	0	**<1**	<1	<1
Calcium	ppm	ASTM D5185(m)	100	**92**	96	102
Phosphorus	ppm	ASTM D5185(m)	670	**591**	637	649
Zinc	ppm	ASTM D5185(m)	850	**735**	729	747
Sulfur	ppm	ASTM D5185(m)	1600	**1503**	1662	1511
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	**2**	2	2
Sodium	ppm	ASTM D5185(m)		**<1**	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	**2**	<1	<1

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	▲ **113295**	▲ 71134	▲ 63837
Particles >6µm		ASTM D7647	>1300	▲ **22125**	▲ 6966	▲ 6548
Particles >14µm		ASTM D7647	>160	● **248**	48	● 218
Particles >21µm		ASTM D7647	>40	**20**	11	43
Particles >38µm		ASTM D7647	>10	**1**	1	1
Particles >71µm		ASTM D7647	>3	**0**	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **24/22/15**	▲ 23/20/13	▲ 23/20/15

OIL ANALYSIS REPORT

Particle Count



Particle Trend



Acid Number



Viscosity @ 100°C



Viscosity @ 40°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.60	**0.99**	0.71	0.61

VISUAL	method		limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	▲ **VLITE**	NONE	▲ VLITE
Yellow Metal	scalar	Visual*	NONE	**NONE**	NONE	NONE
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	NONE
Silt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Debris	scalar	Visual*	NONE	**NONE**	NONE	▲ LIGHT
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	NONE
Appearance	scalar	Visual*	NORML	**NORML**	NORML	NORML
Odor	scalar	Visual*	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES	method		limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	47.9	**46.1**	45.0	46.1
Visc @ 100°C	cSt	ASTM D7279(m)	9.67	**9.2**	8.9	9
Viscosity Index (VI)	Scale	ASTM D2270*	192	**186**	182	180

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					
Bottom					
PrtFilter				*no image*	

CALA

ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : PC0070688 **Received** : 08 Mar 2024
Lab Number : 02620857 **Tested** : 11 Mar 2024
Unique Number : 5745976 **Diagnosed** : 11 Mar 2024 - Kevin Marson
Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, KV100, PrtFilter, TAN Manual)

Vale - Voisey`s Bay
Voisey's Bay Mine Site, P.O. Box 7001, Stn. C Happy Valley
Goose Bay, NL
CA A0P 1C0
Contact: Robert Feltham
robert.feltham@vale.com
T:
F: x:

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.