PROBLEM SUMMARY

Sample Rating Trend



DIRT

Machine Id
427027-4026
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY

Glycol Contamination



Silicon (ppm)



Aluminum (ppm)



RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	ABNORMAL	NORMAL
Aluminum	ppm	ASTM D5185m	>20	▲ **8**	6	16
Silicon	ppm	ASTM D5185m	>25	▲ **34**	16	6
Sodium	ppm	ASTM D5185m		▲ **2023**	▲ 1101	1

Customer Id: GFL663
Sample No.: GFL0079763
Lab Number: 05896030
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	Oil and filter change at the time of sampling has been noted.
Change Filter	---	---	?	Oil and filter change at the time of sampling has been noted.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Dirt Access	---	---	?	We advise that you check the air filter, air induction system, and any areas where dirt may enter the component.
Check Glycol Access	---	---	?	We advise that you check for the source of the coolant leak.

HISTORICAL DIAGNOSIS

07 Mar 2023 Diag: Jonathan Hester

GLYCOL

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Sodium and/or potassium levels are high. The BN result indicates that there is suitable alkalinity remaining in the oil.

view report

21 Sep 2022 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

22 Apr 2021 Diag: Jonathan Hester

GLYCOL

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Sodium and/or potassium levels are high. Test for glycol is negative. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



DIRT

Machine Id
427027-4026
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check for the source of the coolant leak. Check for low coolant level. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
Sodium and/or potassium levels are high. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0079763**	GFL0059570	GFL0031021
Sample Date		Client Info		**15 Jun 2023**	07 Mar 2023	21 Sep 2022
Machine Age	hrs	Client Info		**445312**	15170	13953
Oil Age	hrs	Client Info		**10103**	15170	339545
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**ABNORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**33**	20	35
Chromium	ppm	ASTM D5185m	>20	**<1**	<1	2
Nickel	ppm	ASTM D5185m	>4	**0**	0	0
Titanium	ppm	ASTM D5185m		**4**	11	6
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	▲ **8**	6	16
Lead	ppm	ASTM D5185m	>40	**0**	2	4
Copper	ppm	ASTM D5185m	>330	**<1**	2	12
Tin	ppm	ASTM D5185m	>15	**0**	0	<1
Antimony	ppm	ASTM D5185m		**---**	---	---
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**37**	23	13
Barium	ppm	ASTM D5185m	0	**0**	0	1
Molybdenum	ppm	ASTM D5185m	60	**134**	87	63
Manganese	ppm	ASTM D5185m	0	**0**	<1	<1
Magnesium	ppm	ASTM D5185m	1010	**884**	764	864
Calcium	ppm	ASTM D5185m	1070	**1033**	1165	1219
Phosphorus	ppm	ASTM D5185m	1150	**891**	858	1047
Zinc	ppm	ASTM D5185m	1270	**1208**	1108	1264
Sulfur	ppm	ASTM D5185m	2060	**3760**	3183	3754

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	▲ **34**	16	6
Sodium	ppm	ASTM D5185m		▲ **2023**	▲ 1101	1
Potassium	ppm	ASTM D5185m	>20	**34**	28	28
Glycol	%	*ASTM D2982		**NEG**	NEG	NEG

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.5**	0.3	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**13.4**	11.8	9.3
Sulfation	Abs/.1mm	*ASTM D7415	>30	**22.8**	20.2	20.2

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**17.1**	15.6	15.4
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**12.4**	10.2	8.7

OIL ANALYSIS REPORT

Silicon (ppm)



Aluminum (ppm)



Glycol Contamination



Viscosity @ 100°C



Glycol Contamination



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	**13.5**	13.1	12.8

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0079763 **Received** : 12 Jul 2023
Lab Number : 05896030 **Diagnosed** : 14 Jul 2023
Unique Number : 10551840 **Diagnostician** : Jonathan Hester
Test Package : FLEET (Additional Tests: Glycol)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 663 - Lake Ariel (Scranton Hauling)
17 Industrial Park Rd
Lake Ariel, PA
US 18436
Contact: Eric Merone
emerone@countyrecycling.net
T:
F: