PROBLEM SUMMARY

Sample Rating Trend



FUEL

Machine Id
820020-101305
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY

▲ Viscosity @ 100°C



▲ Fuel Dilution



RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	MARGINAL	NORMAL
Fuel	%	ASTM D3524	>5	▲ **2.4**	▲ 3.9	<1.0
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **10.8**	12.4	12.8

Customer Id: GFL846
Sample No.: GFL0087031
Lab Number: 05941781
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

14 Jun 2023 Diag: Wes Davis

FUEL

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

25 Apr 2023 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

03 Apr 2023 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
820020-101305
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
Light fuel dilution occurring.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0087031**	GFL0083685	GFL0079999
Sample Date		Client Info		**31 Aug 2023**	14 Jun 2023	25 Apr 2023
Machine Age	hrs	Client Info		**0**	0	0
Oil Age	hrs	Client Info		**0**	0	600
Oil Changed		Client Info		**Not Changd**	N/A	Changed
Sample Status				**ABNORMAL**	MARGINAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**13**	11	11
Chromium	ppm	ASTM D5185m	>20	**<1**	<1	<1
Nickel	ppm	ASTM D5185m	>4	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**2**	<1	0
Lead	ppm	ASTM D5185m	>40	**0**	<1	<1
Copper	ppm	ASTM D5185m	>330	**<1**	2	1
Tin	ppm	ASTM D5185m	>15	**<1**	<1	<1
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**0**	3	0
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	60	**56**	57	60
Manganese	ppm	ASTM D5185m	0	**<1**	<1	<1
Magnesium	ppm	ASTM D5185m	1010	**864**	927	927
Calcium	ppm	ASTM D5185m	1070	**1091**	1203	1240
Phosphorus	ppm	ASTM D5185m	1150	**950**	1016	1052
Zinc	ppm	ASTM D5185m	1270	**1137**	1273	1319
Sulfur	ppm	ASTM D5185m	2060	**3235**	3543	2988

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**3**	3	3
Sodium	ppm	ASTM D5185m		**6**	4	4
Potassium	ppm	ASTM D5185m	>20	**0**	3	2
Fuel	%	ASTM D3524	>5	▲ **2.4**	▲ 3.9	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.4**	0.4	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**11.3**	9.9	8.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	**20.8**	21.2	18.5

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**20.1**	18.9	16.1
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**7.3**	8.5	6.9

OIL ANALYSIS REPORT

Fuel Dilution



Fuel Dilution



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **10.8**	12.4	12.8

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0087031 **Received** : 05 Sep 2023
Lab Number : 05941781 **Diagnosed** : 06 Sep 2023
Unique Number : 10632393 **Diagnostician** : Wes Davis
Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 846 - Mayfield Hauling
3426 State Route 45
Mayfield, KY
US 42066
Contact: Jack Lindsey
jack.lindsey@gflenv.com
T: (270)970-3690
F: