PROBLEM SUMMARY

Machine Id
724016-310049
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

Sample Rating Trend



FUEL

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				SEVERE	MARGINAL	ABNORMAL
Fuel	%	ASTM D3524	>5	**11.5**	<1.0	<1.0
Visc @ 100°C	cSt	ASTM D445	15.4	**10.0**	14.8	14.6

Customer Id: GFL821
Sample No.: GFL0090157
Lab Number: 05972513
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Change Filter	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

24 Jun 2023 Diag: Doug Bogart

WEAR

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.The chromium level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

25 Apr 2023 Diag: Don Baldridge

WEAR

No corrective action is recommended at this time. Resample at the next service interval to monitor.The chromium level has decreased, but is still abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

14 Mar 2023 Diag: Don Baldridge

WEAR

No corrective action is recommended at this time. Resample at the next service interval to monitor.The chromium level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
724016-310049
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0090157**	GFL0076785	GFL0065402
Sample Date		Client Info		**04 Oct 2023**	24 Jun 2023	25 Apr 2023
Machine Age	hrs	Client Info		**9271**	8710	8604
Oil Age	hrs	Client Info		**150**	600	200
Oil Changed		Client Info		**N/A**	Changed	Not Changd
Sample Status				**SEVERE**	MARGINAL	ABNORMAL

CONTAMINATION	method	limit/base	current	history1	history2
Glycol	WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	**27**	62	54
Chromium	ppm	ASTM D5185m	>5	**<1**	▲ 8	▲ 7
Nickel	ppm	ASTM D5185m	>2	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>30	**8**	4	2
Lead	ppm	ASTM D5185m	>30	**<1**	0	0
Copper	ppm	ASTM D5185m	>150	**3**	2	1
Tin	ppm	ASTM D5185m	>5	**0**	<1	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**5**	3	4
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	60	**51**	61	58
Manganese	ppm	ASTM D5185m	0	**<1**	1	1
Magnesium	ppm	ASTM D5185m	1010	**783**	962	905
Calcium	ppm	ASTM D5185m	1070	**847**	1110	1036
Phosphorus	ppm	ASTM D5185m	1150	**851**	1045	975
Zinc	ppm	ASTM D5185m	1270	**1062**	1311	1199
Sulfur	ppm	ASTM D5185m	2060	**2908**	3646	3439

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	**8**	5	4
Sodium	ppm	ASTM D5185m		**39**	1	2
Potassium	ppm	ASTM D5185m	>20	**7**	1	0
Fuel	%	ASTM D3524	>5	● **11.5**	<1.0	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.9**	2.3	1.8
Nitration	Abs/cm	*ASTM D7624	>20	**7.6**	8.4	6.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	**20.0**	22.7	19.0

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**15.5**	14.0	12.6
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**7.1**	9.3	8.0

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 100°C



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **10.0**	14.8	14.6

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0090157 **Received** : 09 Oct 2023
Lab Number : 05972513 **Diagnosed** : 11 Oct 2023
Unique Number : 10684463 **Diagnostician** : Jonathan Hester
Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 821 - Ozarks Hauling
33924 Olath Drive
Lebanon, MO
US 65536
Contact: Landen Johnson
landen.johnson@gflenv.com
T: (417)664-0010
F: