# PROBLEM SUMMARY

Sample Rating Trend



**GLYCOL**

Machine Id
**721024-361461**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## COMPONENT CONDITION SUMMARY

▲ Glycol Contamination




▲ Ferrous Alloys




## RECOMMENDATION

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

## PROBLEMATIC TEST RESULTS

| Sample Status | | | | **ABNORMAL** | NORMAL | NORMAL |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >100 | ▲ **74** | 4 | 2 |
| Sodium | ppm | ASTM D5185m | | ▲ **377** | 1 | <1 |
| Potassium | ppm | ASTM D5185m | >20 | ▲ **427** | 4 | 5 |

**Customer Id:** GFL821
**Sample No.:** GFL0090343
**Lab Number:** 06033303
**Test Package:** FLEET

*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

*To change component or sample information:*
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

## RECOMMENDED ACTIONS

| Action | Status | Date | Done By | Description |
|---|---|---|---|---|
| Change Fluid | --- | --- | ? | Oil and filter change at the time of sampling has been noted. |
| Change Filter | --- | --- | ? | Oil and filter change at the time of sampling has been noted. |
| Resample | --- | --- | ? | We recommend an early resample to monitor this condition. |
| Check Glycol Access | --- | --- | ? | We advise that you check for the source of the coolant leak. |

## HISTORICAL DIAGNOSIS

**05 Dec 2023 Diag: Sean Felton**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**31 Oct 2023 Diag: Wes Davis**

NORMAL

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

**19 Oct 2023 Diag: Wes Davis**

NORMAL

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

# OIL ANALYSIS REPORT

Sample Rating Trend



**GLYCOL**

Machine Id
**721024-361461**
Component
**Diesel Engine**
Fluid
**PETRO CANADA DURON SHP 15W40 (--- GAL)**

## DIAGNOSIS

**Recommendation**
We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

**Wear**
The iron level is marginal.

**Contamination**
Sodium and/or potassium levels are high.

**Fluid Condition**
The BN result indicates that there is suitable alkalinity remaining in the oil.

| SAMPLE INFORMATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Sample Number | | Client Info | | **GFL0090343** | GFL0090330 | GFL0090171 |
| Sample Date | | Client Info | | **11 Dec 2023** | 05 Dec 2023 | 31 Oct 2023 |
| Machine Age | hrs | Client Info | | **7055** | 16414 | 6790 |
| Oil Age | hrs | Client Info | | **600** | 300 | 150 |
| Oil Changed | | Client Info | | **Changed** | Not Changd | Not Changd |
| Sample Status | | | | **ABNORMAL** | NORMAL | NORMAL |

| CONTAMINATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Fuel | | WC Method | >5 | **<1.0** | <1.0 | <1.0 |
| Water | | WC Method | >0.2 | **NEG** | NEG | NEG |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Iron | ppm | ASTM D5185m | >100 | ▲ **74** | 4 | 2 |
| Chromium | ppm | ASTM D5185m | >20 | **5** | <1 | <1 |
| Nickel | ppm | ASTM D5185m | >4 | **<1** | 0 | <1 |
| Titanium | ppm | ASTM D5185m | | **<1** | 11 | 0 |
| Silver | ppm | ASTM D5185m | >3 | **0** | 0 | <1 |
| Aluminum | ppm | ASTM D5185m | >20 | **4** | 2 | 1 |
| Lead | ppm | ASTM D5185m | >40 | **4** | <1 | 0 |
| Copper | ppm | ASTM D5185m | >330 | **6** | 1 | <1 |
| Tin | ppm | ASTM D5185m | >15 | **2** | <1 | 0 |
| Vanadium | ppm | ASTM D5185m | | **0** | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | **<1** | <1 | <1 |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Boron | ppm | ASTM D5185m | 0 | **1** | 212 | 2 |
| Barium | ppm | ASTM D5185m | 0 | **11** | 0 | 4 |
| Molybdenum | ppm | ASTM D5185m | 60 | **129** | 67 | 58 |
| Manganese | ppm | ASTM D5185m | 0 | **1** | 0 | 0 |
| Magnesium | ppm | ASTM D5185m | 1010 | **898** | 700 | 862 |
| Calcium | ppm | ASTM D5185m | 1070 | **1027** | 1507 | 994 |
| Phosphorus | ppm | ASTM D5185m | 1150 | **995** | 771 | 898 |
| Zinc | ppm | ASTM D5185m | 1270 | **1183** | 862 | 1145 |
| Sulfur | ppm | ASTM D5185m | 2060 | **3242** | 3068 | 3192 |

| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Silicon | ppm | ASTM D5185m | >25 | **11** | 4 | 5 |
| Sodium | ppm | ASTM D5185m | | ▲ **377** | 1 | <1 |
| Potassium | ppm | ASTM D5185m | >20 | ▲ **427** | 4 | 5 |
| Glycol | % | *ASTM D2982 | | **NEG** | NEG | NEG |

| INFRA-RED | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Soot % | % | *ASTM D7844 | >3 | **1.3** | 0.1 | 0.1 |
| Nitration | Abs/cm | *ASTM D7624 | >20 | **11.2** | 4.1 | 4.2 |
| Sulfation | Abs/.1mm | *ASTM D7415 | >30 | **21.3** | 17.3 | 17.5 |

| FLUID DEGRADATION | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Oxidation | Abs/.1mm | *ASTM D7414 | >25 | **17.0** | 12.7 | 12.9 |
| Base Number (BN) | mg KOH/g | ASTM D2896 | 9.8 | **10.0** | 9.0 | 9.2 |

# OIL ANALYSIS REPORT

Glycol Contamination




Base Number




Viscosity @ 100°C




Glycol Contamination




| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Silt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Debris | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | **NONE** | NONE | NONE |
| Appearance | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Odor | scalar | *Visual | NORML | **NORML** | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.2 | **NEG** | NEG | NEG |
| Free Water | scalar | *Visual | | **NEG** | NEG | NEG |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Visc @ 100°C | cSt | ASTM D445 | 15.4 | **13.3** | 14.5 | 14.4 |

## GRAPHS

Ferrous Alloys




Non-ferrous Metals




Viscosity @ 100°C




Base Number




Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513
**Sample No.** : GFL0090343 **Recieved** : 13 Dec 2023
**Lab Number** : 06033303 **Diagnosed** : 18 Dec 2023
**Unique Number** : 10783094 **Diagnostician** : Jonathan Hester
**Test Package** : FLEET ( Additional Tests: Glycol )

*To discuss this sample report, contact Customer Service at 1-800-237-1369.*
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
*Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)*


**GFL Environmental - 821 - Ozarks Hauling**
33924 Olath Drive
Lebanon, MO
US 65536
Contact: Landen Johnson
landen.johnson@gflenv.com
T: (417)664-0010
F: