OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL

Machine Id
633722
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 10W30 (--- QTS)

DIAGNOSIS

Recommendation
Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear
Metal levels are typical for a new component breaking in.

Contamination
Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0093335**	PCA0093320	PCA0078797
Sample Date		Client Info		**17 Nov 2023**	10 Aug 2023	14 Apr 2023
Machine Age	mls	Client Info		**61175**	47801	31027
Oil Age	mls	Client Info		**0**	0	0
Oil Changed		Client Info		**Changed**	Not Changd	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**47**	30	91
Chromium	ppm	ASTM D5185m	>20	**2**	1	3
Nickel	ppm	ASTM D5185m	>4	**<1**	0	0
Titanium	ppm	ASTM D5185m		**7**	6	<1
Silver	ppm	ASTM D5185m	>3	**<1**	<1	0
Aluminum	ppm	ASTM D5185m	>20	**17**	15	39
Lead	ppm	ASTM D5185m	>40	**<1**	<1	<1
Copper	ppm	ASTM D5185m	>330	**13**	9	51
Tin	ppm	ASTM D5185m	>15	**1**	<1	3
Vanadium	ppm	ASTM D5185m		**<1**	<1	0
Cadmium	ppm	ASTM D5185m		**<1**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	**4**	5	18
Barium	ppm	ASTM D5185m	0	**13**	0	0
Molybdenum	ppm	ASTM D5185m	50	**58**	52	18
Manganese	ppm	ASTM D5185m	0	**2**	<1	3
Magnesium	ppm	ASTM D5185m	950	**956**	936	714
Calcium	ppm	ASTM D5185m	1050	**1280**	1259	1393
Phosphorus	ppm	ASTM D5185m	995	**1026**	990	722
Zinc	ppm	ASTM D5185m	1180	**1302**	1254	887
Sulfur	ppm	ASTM D5185m	2600	**3106**	3558	3057

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**12**	11	17
Sodium	ppm	ASTM D5185m		**1**	4	4
Potassium	ppm	ASTM D5185m	>20	**49**	34	111

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.5**	0.3	0.5
Nitration	Abs/cm	*ASTM D7624	>20	**11.7**	10.1	13.2
Sulfation	Abs/.1mm	*ASTM D7415	>30	**24.7**	20.7	27.9

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**21.8**	17.5	24.8
Base Number (BN)	mg KOH/g	ASTM D2896		**4.9**	6.7	3.9

OIL ANALYSIS REPORT





VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	12.00	**12.1**	11.9	11.9

GRAPHS

















Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0093335 **Recieved** : 15 Dec 2023
Lab Number : 06036551 **Diagnosed** : 18 Dec 2023
Unique Number : 10791780 **Diagnostician** : Wes Davis
Test Package : MOB 1 (Additional Tests: TBN)

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #117
2666 LEISCZS BRIDGE RD
LEESPORT, PA
US 19533
Contact: JAMEY RITZ
jritz@millertransgroup.com
T:
F: