PROBLEM SUMMARY

Machine Id
427087-402443
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

Sample Rating Trend



FUEL

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. Resample at the next service interval to monitor. (Customer Sample Comment: Engine oil sample)

PROBLEMATIC TEST RESULTS

Sample Status				SEVERE	ABNORMAL	NORMAL
Fuel	%	ASTM D3524	>3.0	**12.0**	<1.0	<1.0
Visc @ 100°C	cSt	ASTM D445	15.4	**10.7**	14.0	14.3

Customer Id: GFL865
Sample No.: GFL0100552
Lab Number: 06059972
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Change Filter	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

29 Dec 2023 Diag: Jonathan Hester

GLYCOL

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Sodium and/or potassium levels are high. The BN result indicates that there is suitable alkalinity remaining in the oil.

view report

19 Jan 2023 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

03 Jan 2023 Diag: Wes Davis

NORMAL

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Machine Id
427087-402443
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

Sample Rating Trend



FUEL

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. Resample at the next service interval to monitor. (Customer Sample Comment: Engine oil sample)

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0100552**	GFL0103951	GFL0065233
Sample Date		Client Info		**08 Jan 2024**	29 Dec 2023	19 Jan 2023
Machine Age	hrs	Client Info		**18356**	328962	326297
Oil Age	hrs	Client Info		**18356**	328962	413
Oil Changed		Client Info		**Not Changd**	Changed	Changed
Sample Status				**SEVERE**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	**5**	19	8
Chromium	ppm	ASTM D5185m	>20	**0**	0	<1
Nickel	ppm	ASTM D5185m	>5	**0**	0	0
Titanium	ppm	ASTM D5185m	>2	**0**	0	0
Silver	ppm	ASTM D5185m	>2	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**4**	4	<1
Lead	ppm	ASTM D5185m	>40	**<1**	8	<1
Copper	ppm	ASTM D5185m	>330	**12**	51	2
Tin	ppm	ASTM D5185m	>15	**0**	0	<1
Vanadium	ppm	ASTM D5185m		**<1**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**34**	240	0
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	60	**55**	100	62
Manganese	ppm	ASTM D5185m	0	**<1**	<1	<1
Magnesium	ppm	ASTM D5185m	1010	**723**	366	965
Calcium	ppm	ASTM D5185m	1070	**1056**	963	1089
Phosphorus	ppm	ASTM D5185m	1150	**940**	1009	1085
Zinc	ppm	ASTM D5185m	1270	**1105**	1209	1275
Sulfur	ppm	ASTM D5185m	2060	**2866**	3330	3225

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**7**	15	6
Sodium	ppm	ASTM D5185m		**19**	▲ 118	<1
Potassium	ppm	ASTM D5185m	>20	**23**	▲ 166	2
Fuel	%	ASTM D3524	>3.0	● **12.0**	<1.0	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	**0.1**	0.1	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**5.1**	5.1	5.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	**17.6**	20.1	18.2

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**13.2**	14.0	13.3
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**8.3**	11.8	9.1

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 100°C



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **10.7**	14.0	14.3

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0100552 **Recieved** : 12 Jan 2024
Lab Number : 06059972 **Diagnosed** : 16 Jan 2024
Unique Number : 10831354 **Diagnostician** : Don Baldridge
Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 865 - East Mount Hauling
7213 East Mount Houston Road
Houston, TX
US 77050
Contact: Jose Gonzalez
jgonzalez2@gflenv.com
T:
F:

Report Id: GFL865 [WUSCAR] 06059972 (Generated: 01/16/2024 11:15:36) Rev: 1

Submitted By: TECHNICIAN ACCOUNT