PROBLEM SUMMARY

Area
(P630585)
Machine Id
10554
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (8 GAL)

Sample Rating Trend



FUEL

COMPONENT CONDITION SUMMARY

▲ Fuel Dilution



▲ Viscosity @ 100°C



RECOMMENDATION

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**SEVERE**	SEVERE	SEVERE
Fuel	%	ASTM D3524	>5	▲ **9.6**	▲ 12.0	▲ 8.9
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **11.1**	▲ 10.4	▲ 10.9

Customer Id: GFL015
Sample No.: GFL0096954
Lab Number: 06134469
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil from the component if this has not already been done.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

04 May 2023 Diag: Wes Davis

FUEL

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

view report

17 Oct 2022 Diag: Don Baldridge

FUEL

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

view report

11 Jan 2022 Diag: Jonathan Hester

FUEL

Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Area
(P630585)
Machine Id
10554
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (8 GAL)

DIAGNOSIS

▲ Recommendation

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

▲ Contamination

There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

▲ Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0096954**	GFL0080072	GFL0060309
Sample Date		Client Info		**29 Mar 2024**	04 May 2023	17 Oct 2022
Machine Age	hrs	Client Info		**7855**	6268	5715
Oil Age	hrs	Client Info		**45248**	6268	5715
Oil Changed		Client Info		**Not Changd**	Changed	Changed
Sample Status				**SEVERE**	SEVERE	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**9**	12	18
Chromium	ppm	ASTM D5185m	>20	**<1**	<1	1
Nickel	ppm	ASTM D5185m	>4	**0**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	<1
Silver	ppm	ASTM D5185m	>3	**0**	0	<1
Aluminum	ppm	ASTM D5185m	>20	**2**	<1	4
Lead	ppm	ASTM D5185m	>40	**0**	0	0
Copper	ppm	ASTM D5185m	>330	**<1**	<1	1
Tin	ppm	ASTM D5185m	>15	**<1**	0	<1
Antimony	ppm	ASTM D5185m		**---**	---	---
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**14**	6	3
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	60	**61**	48	51
Manganese	ppm	ASTM D5185m	0	**<1**	0	1
Magnesium	ppm	ASTM D5185m	1010	**667**	735	774
Calcium	ppm	ASTM D5185m	1070	**1037**	923	926
Phosphorus	ppm	ASTM D5185m	1150	**826**	818	818
Zinc	ppm	ASTM D5185m	1270	**998**	1016	1041
Sulfur	ppm	ASTM D5185m	2060	**2833**	2594	2651

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**3**	3	5
Sodium	ppm	ASTM D5185m		**4**	5	6
Potassium	ppm	ASTM D5185m	>20	**2**	3	11
Fuel	%	ASTM D3524	>5	**▲ 9.6**	▲ 12.0	▲ 8.9

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.3**	0.3	0.5
Nitration	Abs/cm	*ASTM D7624	>20	**9.3**	10.0	11.6
Sulfation	Abs/.1mm	*ASTM D7415	>30	**19.0**	19.9	22.9

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**17.1**	17.6	20.9
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**7.0**	6.6	6.9

OIL ANALYSIS REPORT

Fuel Dilution



Viscosity @ 100°C



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **11.1**	▲ 10.4	▲ 10.9

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0096954
Lab Number : 06134469
Unique Number : 10953934
Test Package : FLEET (Additional Tests: PercentFuel)

Received : 01 Apr 2024
Tested : 03 Apr 2024
Diagnosed : 03 Apr 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 015 - Columbia
7800 Farrow Road
Columbia, SC
US 29203-3219
Contact: NOEL MATTHEWS
nmatthewsjr@gflenv.com
T: (803)935-0249
F: (803)935-0244

Report Id: GFL015 [WUSCAR] 06134469 (Generated: 04/03/2024 09:57:38) Rev: 1

Submitted By: DAKOTA DABNEY