PROBLEM SUMMARY

Sample Rating Trend



FUEL

Machine Id
429042-402342
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY

▲ Fuel Dilution



▲ Viscosity @ 100°C



RECOMMENDATION

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**SEVERE**	ABNORMAL	ABNORMAL
Fuel	%	ASTM D3524	>5	▲ **8.3**	▲ 7.6	▲ 7.4
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **11.2**	▲ 11.3	▲ 11.5

Customer Id: GFL822
Sample No.: GFL0109124
Lab Number: 06137050
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

FUEL

18 Mar 2024 Diag: Wes Davis

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

view report

FUEL

19 Feb 2024 Diag: Wes Davis

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

view report

FUEL

08 Dec 2023 Diag: Wes Davis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
429042-402342
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0109124**	GFL0109168	GFL0109236
Sample Date		Client Info		**28 Mar 2024**	18 Mar 2024	19 Feb 2024
Machine Age	hrs	Client Info		**16916**	16826	16724
Oil Age	hrs	Client Info		**600**	150	150
Oil Changed		Client Info		**Changed**	Not Changd	Not Changd
Sample Status				**SEVERE**	ABNORMAL	ABNORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>110	**15**	25	14
Chromium	ppm	ASTM D5185m	>4	**<1**	1	<1
Nickel	ppm	ASTM D5185m	>2	**0**	<1	0
Titanium	ppm	ASTM D5185m		**0**	<1	<1
Silver	ppm	ASTM D5185m	>2	**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	**2**	3	2
Lead	ppm	ASTM D5185m	>45	**1**	3	<1
Copper	ppm	ASTM D5185m	>85	**2**	2	<1
Tin	ppm	ASTM D5185m	>4	**<1**	1	0
Vanadium	ppm	ASTM D5185m		**0**	<1	0
Cadmium	ppm	ASTM D5185m		**0**	<1	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**2**	0	0
Barium	ppm	ASTM D5185m	0	**0**	1	0
Molybdenum	ppm	ASTM D5185m	60	**56**	85	56
Manganese	ppm	ASTM D5185m	0	**<1**	1	<1
Magnesium	ppm	ASTM D5185m	1010	**911**	1309	949
Calcium	ppm	ASTM D5185m	1070	**999**	1539	1025
Phosphorus	ppm	ASTM D5185m	1150	**1001**	1460	1011
Zinc	ppm	ASTM D5185m	1270	**1213**	1749	1209
Sulfur	ppm	ASTM D5185m	2060	**3203**	4552	2949

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>30	**4**	9	7
Sodium	ppm	ASTM D5185m		**4**	5	11
Potassium	ppm	ASTM D5185m	>20	**0**	3	4
Fuel	%	ASTM D3524	>5	▲ **8.3**	▲ 7.6	▲ 7.4

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.7**	0.6	0.4
Nitration	Abs/cm	*ASTM D7624	>20	**9.8**	9.2	8.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	**20.0**	19.7	18.8

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**17.6**	16.9	15.5
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**7.0**	7.3	8.1

OIL ANALYSIS REPORT

Fuel Dilution



FT-IR (Direct Trend)



FT-IR (Direct Trend)



Base Number



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	▲ **11.2**	▲ 11.3	▲ 11.5

GRAPHS

Ferrous Alloys



Non-ferrous Metals



▲ Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0109124
Lab Number : 06137050
Unique Number : 10956515
Test Package : FLEET (Additional Tests: PercentFuel)

Received : 03 Apr 2024
Tested : 05 Apr 2024
Diagnosed : 05 Apr 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 822 - Springfield Hauling
2120 West Bennett Street
Springfield, MO
US 65807
Contact: Dennis Moore
dennis.moore@gflenv.com
T: (417)403-3641
F:

Report Id: GFL822 [WUSCAR] 06137050 (Generated: 04/05/2024 08:12:27) Rev: 1

Submitted By: Dennis Moore