OIL ANALYSIS REPORT

Area
(34718UA)
Machine Id
828100
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

Sample Rating Trend



FUEL

DIAGNOSIS

Recommendation
The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0116561**	GFL0098180	GFL0108328
Sample Date		Client Info		**02 Apr 2024**	16 Jan 2024	06 Jan 2024
Machine Age	hrs	Client Info		**12130**	12059	12030
Oil Age	hrs	Client Info		**12130**	12059	12030
Oil Changed		Client Info		**Changed**	Not Changd	N/A
Sample Status				**ABNORMAL**	SEVERE	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**19**	31	▲ 132
Chromium	ppm	ASTM D5185m	>20	**1**	1	8
Nickel	ppm	ASTM D5185m	>4	**0**	<1	4
Titanium	ppm	ASTM D5185m		**<1**	0	<1
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>20	**6**	4	16
Lead	ppm	ASTM D5185m	>40	**0**	0	0
Copper	ppm	ASTM D5185m	>330	**1**	1	4
Tin	ppm	ASTM D5185m	>15	**0**	0	<1
Vanadium	ppm	ASTM D5185m		**<1**	<1	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**17**	9	10
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	60	**51**	58	58
Manganese	ppm	ASTM D5185m	0	**<1**	<1	2
Magnesium	ppm	ASTM D5185m	1010	**896**	982	863
Calcium	ppm	ASTM D5185m	1070	**1089**	1103	991
Phosphorus	ppm	ASTM D5185m	1150	**910**	1090	988
Zinc	ppm	ASTM D5185m	1270	**1194**	1311	1139
Sulfur	ppm	ASTM D5185m	2060	**3658**	3381	2634

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**7**	6	9
Sodium	ppm	ASTM D5185m		**2**	2	8
Potassium	ppm	ASTM D5185m	>20	**6**	4	12
Fuel	%	ASTM D3524	>5	▲ **5.2**	▲ 25.5	▲ 5.4

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.5**	1.5	▲ 6
Nitration	Abs/cm	*ASTM D7624	>20	**6.3**	6.8	21.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	**17.8**	20.2	37.6

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**13.1**	13.0	32.0
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**9.1**	8.9	▲ 0.0

OIL ANALYSIS REPORT

Fuel Dilution



FT-IR (Direct Trend)



Base Number



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	**12.5**	14.0	14.1

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0116561
Lab Number : 06138420
Unique Number : 10963228
Test Package : FLEET (Additional Tests: PercentFuel)

Received : 04 Apr 2024
Tested : 08 Apr 2024
Diagnosed : 08 Apr 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 652 - Fredericksburg Hauling
10954 Houser Drive
Fredericksburg, VA
US 22408
Contact: WILLIAM MILO
wmilo@gflenv.com
T:
F:

Report Id: GFL652 [WUSCAR] 06138420 (Generated: 04/08/2024 10:23:42) Rev: 1

Submitted By: TECHNICIAN ACCOUNT