OIL ANALYSIS REPORT

Sample Rating Trend



GLYCOL

Machine Id
513414
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 10W30 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check for possible coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
Sodium and/or potassium levels are high.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0121483**	PCA0085217	PCA0053285
Sample Date		Client Info		**27 Mar 2024**	29 Dec 2022	23 Jun 2021
Machine Age	mls	Client Info		**160469**	105405	50554
Oil Age	mls	Client Info		**160469**	15000	50554
Oil Changed		Client Info		**Not Changd**	Changed	Changed
Sample Status				**ABNORMAL**	NORMAL	ABNORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**35**	36	80
Chromium	ppm	ASTM D5185m	>20	**1**	2	4
Nickel	ppm	ASTM D5185m	>4	**0**	0	1
Titanium	ppm	ASTM D5185m		**3**	5	4
Silver	ppm	ASTM D5185m	>3	**0**	0	<1
Aluminum	ppm	ASTM D5185m	>20	**16**	16	28
Lead	ppm	ASTM D5185m	>40	**0**	0	<1
Copper	ppm	ASTM D5185m	>330	**2**	3	13
Tin	ppm	ASTM D5185m	>15	**<1**	<1	3
Antimony	ppm	ASTM D5185m		**---**	---	0
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	**7**	0	10
Barium	ppm	ASTM D5185m	0	**0**	0	0
Molybdenum	ppm	ASTM D5185m	50	**63**	51	57
Manganese	ppm	ASTM D5185m	0	**<1**	<1	2
Magnesium	ppm	ASTM D5185m	950	**910**	750	957
Calcium	ppm	ASTM D5185m	1050	**1188**	1067	1270
Phosphorus	ppm	ASTM D5185m	995	**1020**	833	1002
Zinc	ppm	ASTM D5185m	1180	**1227**	1022	1263
Sulfur	ppm	ASTM D5185m	2600	**3426**	2978	2552

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**5**	6	7
Sodium	ppm	ASTM D5185m		**15**	2	5
Potassium	ppm	ASTM D5185m	>20	▲ **137**	21	▲ 74
Glycol	%	*ASTM D2982		**NEG**	NEG	NEG

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**1.1**	1.2	1.1
Nitration	Abs/cm	*ASTM D7624	>20	**12.8**	12.0	12.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	**24.4**	23.4	27.5

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**21.7**	20.1	22.8
Base Number (BN)	mg KOH/g	ASTM D2896		**7.3**	7.8	---

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Glycol Contamination



Viscosity @ 100°C



Glycol Contamination



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	12.00	**11.5**	11.6	11.4

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0121483 **Received** : 10 Apr 2024
Lab Number : 06143824 **Tested** : 12 Apr 2024
Unique Number : 10968632 **Diagnosed** : 12 Apr 2024 - Jonathan Hester
Test Package : MOB 1 (Additional Tests: Glycol, TBN)

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #118
2196 BENNETT ROAD
PHILADELPHIA, PA
US 19116
Contact: ROSTY VITER
rviter@millertransgroup.com
T: (215)552-9832
F: (215)552-9892