PROBLEM SUMMARY

Machine Id
269
Component
Diesel Engine
Fluid
{not provided} (--- GAL)

Sample Rating Trend



SOOT

COMPONENT CONDITION SUMMARY

▲ Fuel Dilution



▲ Soot %



▲ Viscosity @ 100°C



RECOMMENDATION

We advise that you check the fuel injection system. We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.

PROBLEMATIC TEST RESULTS

Sample Status				**SEVERE**	---	---
Fuel	%	ASTM D3524	>5	▲ **31.7**	---	---
Soot %	%	*ASTM D7844	>3	▲ **8.8**	---	---
Base Number (BN)	mg KOH/g	ASTM D2896		▲ **0.0**	---	---
Visc @ 100°C	cSt	ASTM D445		▲ **9.5**	---	---

Customer Id: GFL112
Sample No.: GFL0110403
Lab Number: 06146335
Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:
Jonathan Hester +1 919-379-4092 x4092
jhester@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Change Filter	---	---	?	We recommend that you drain the oil and perform a filter service on this component if not already done.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Alert	---	---	?	NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.
Check Combustion	---	---	?	We advise that you check for faulty combustion, plugged air filters, or aftercoolers.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

OIL ANALYSIS REPORT

Sample Rating Trend



SOOT

Machine Id
269
Component
Diesel Engine
Fluid
{not provided} (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value.

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil. There is an abnormal amount of solids and carbon present in the oil.

Fluid Condition
Fuel is present in the oil and is lowering the viscosity. The BN level is low. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0110403**	---	---
Sample Date		Client Info		**10 Apr 2024**	---	---
Machine Age	hrs	Client Info		**0**	---	---
Oil Age	hrs	Client Info		**0**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**SEVERE**	---	---

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	---	---
Glycol		WC Method		**NEG**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**55**	---	---
Chromium	ppm	ASTM D5185m	>20	**3**	---	---
Nickel	ppm	ASTM D5185m	>4	**1**	---	---
Titanium	ppm	ASTM D5185m		**0**	---	---
Silver	ppm	ASTM D5185m	>3	**0**	---	---
Aluminum	ppm	ASTM D5185m	>20	**2**	---	---
Lead	ppm	ASTM D5185m	>40	**2**	---	---
Copper	ppm	ASTM D5185m	>330	**2**	---	---
Tin	ppm	ASTM D5185m	>15	**<1**	---	---
Vanadium	ppm	ASTM D5185m		**0**	---	---
Cadmium	ppm	ASTM D5185m		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**4**	---	---
Barium	ppm	ASTM D5185m		**0**	---	---
Molybdenum	ppm	ASTM D5185m		**36**	---	---
Manganese	ppm	ASTM D5185m		**<1**	---	---
Magnesium	ppm	ASTM D5185m		**593**	---	---
Calcium	ppm	ASTM D5185m		**673**	---	---
Phosphorus	ppm	ASTM D5185m		**643**	---	---
Zinc	ppm	ASTM D5185m		**769**	---	---
Sulfur	ppm	ASTM D5185m		**2240**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**4**	---	---
Sodium	ppm	ASTM D5185m		**1**	---	---
Potassium	ppm	ASTM D5185m	>20	**2**	---	---
Fuel	%	ASTM D3524	>5	▲ **31.7**	---	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	▲ **8.8**	---	---
Nitration	Abs/cm	*ASTM D7624	>20	**22.7**	---	---
Sulfation	Abs/.1mm	*ASTM D7415	>30	**37.0**	---	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**29.7**	---	---
Base Number (BN)	mg KOH/g	ASTM D2896		▲ **0.0**	---	---

OIL ANALYSIS REPORT

Fuel Dilution



FT-IR (Direct Trend)



Soot %



Base Number



Viscosity @ 100°C

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	---	---
Yellow Metal	scalar	*Visual	NONE	**NONE**	---	---
Precipitate	scalar	*Visual	NONE	**NONE**	---	---
Silt	scalar	*Visual	NONE	**NONE**	---	---
Debris	scalar	*Visual	NONE	**NONE**	---	---
Sand/Dirt	scalar	*Visual	NONE	**NONE**	---	---
Appearance	scalar	*Visual	NORML	**NORML**	---	---
Odor	scalar	*Visual	NORML	**NORML**	---	---
Emulsified Water	scalar	*Visual	>0.2	**NEG**	---	---
Free Water	scalar	*Visual		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445		▲ **9.5**	---	---

GRAPHS

Ferrous Alloys



Non-ferrous Metals

Viscosity @ 100°C



Base Number



ANAB ACCREDITED ISO/IEC 17025 TESTING LABORATORY
Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0110403
Lab Number : 06146335
Unique Number : 10976413
Test Package : FLEET (Additional Tests: FuelDilution, PercentFuel)

Received : 11 Apr 2024
Tested : 17 Apr 2024
Diagnosed : 17 Apr 2024 - Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 112 - New Bern
705 Airport Road
New Bern, NC
US 28560
Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com
T:
F: