OIL ANALYSIS REPORT

Sample Rating Trend



GLYCOL

Machine Id
428068-402225.1
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
Sodium and/or potassium levels are high.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**GFL0093437**	GFL0109426	GFL0095309
Sample Date		Client Info		**29 May 2024**	29 Apr 2024	21 Mar 2024
Machine Age	hrs	Client Info		**18710**	18564	18449
Oil Age	hrs	Client Info		**261**	115	650
Oil Changed		Client Info		**Not Changd**	Not Changd	Changed
Sample Status				**ABNORMAL**	ABNORMAL	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	**<1.0**	<1.0	<1.0
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	**24**	24	8
Chromium	ppm	ASTM D5185m	>20	**1**	1	1
Nickel	ppm	ASTM D5185m	>4	**0**	<1	<1
Titanium	ppm	ASTM D5185m		**2**	2	8
Silver	ppm	ASTM D5185m	>3	**0**	<1	<1
Aluminum	ppm	ASTM D5185m	>20	**3**	4	2
Lead	ppm	ASTM D5185m	>40	**0**	<1	1
Copper	ppm	ASTM D5185m	>330	**<1**	2	<1
Tin	ppm	ASTM D5185m	>15	**<1**	<1	1
Vanadium	ppm	ASTM D5185m		**0**	<1	<1
Cadmium	ppm	ASTM D5185m		**0**	<1	<1

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**25**	4	13
Barium	ppm	ASTM D5185m	0	**0**	0	1
Molybdenum	ppm	ASTM D5185m	60	**64**	69	59
Manganese	ppm	ASTM D5185m	0	**<1**	<1	1
Magnesium	ppm	ASTM D5185m	1010	**805**	876	900
Calcium	ppm	ASTM D5185m	1070	**899**	1027	1121
Phosphorus	ppm	ASTM D5185m	1150	**1089**	1029	1012
Zinc	ppm	ASTM D5185m	1270	**1065**	1181	1211
Sulfur	ppm	ASTM D5185m	2060	**4348**	3141	3305

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**6**	8	4
Sodium	ppm	ASTM D5185m		▲ **101**	▲ 74	20
Potassium	ppm	ASTM D5185m	>20	▲ **135**	▲ 93	27
Glycol	%	*ASTM D2982		**NEG**	NEG	NEG

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	**0.4**	0.3	0.1
Nitration	Abs/cm	*ASTM D7624	>20	**7.5**	6.7	5.0
Sulfation	Abs/.1mm	*ASTM D7415	>30	**32.3**	18.2	17.4

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**33.7**	13.8	13.4
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**8.3**	9.0	9.4

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



Glycol Contamination



Viscosity @ 100°C



Glycol Contamination



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	▲ MODER	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	**14.3**	13.9	14.4

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : GFL0093437
Lab Number : 06196427
Unique Number : 11058550
Test Package : FLEET (Additional Tests: Glycol)

Received : 31 May 2024
Tested : 03 Jun 2024
Diagnosed : 03 Jun 2024 - Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 891 - Oklahoma City Hauling
1001 South Rockwell
Oklahoma City, OK
US 73128
Contact: Andy Smith
andrew.smith@gflenv.com
T: (405)306-1651
F:

Report Id: GFL891 [WUSCAR] 06196427 (Generated: 06/03/2024 16:26:12) Rev: 1

Submitted By: Andy Smith