OIL DIAGNOSTICS

OIL ANALYSIS REPORT

Sample Rating Trend



SOOT

Machine Id
FREIGHTLINER 86
Component
Diesel Engine
Fluid
PETRO CANADA DURON SHP 15W40 (13 LTR)

DIAGNOSIS

Recommendation
The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a moderate amount of fuel present in the oil. Light concentration of carbon/soot present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**PCA0117394**	PCA0104966	PCA0102657
Sample Date		Client Info		**02 Jul 2024**	01 May 2024	24 Jul 2023
Machine Age	mls	Client Info		**575831**	547476	444369
Oil Age	mls	Client Info		**25000**	25000	24577
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**ABNORMAL**	ABNORMAL	ABNORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	▲ 0.06

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	**61**	49	41
Chromium	ppm	ASTM D5185m	>5	**3**	2	2
Nickel	ppm	ASTM D5185m	>2	**<1**	0	0
Titanium	ppm	ASTM D5185m		**0**	0	0
Silver	ppm	ASTM D5185m	>3	**0**	0	0
Aluminum	ppm	ASTM D5185m	>30	**2**	<1	<1
Lead	ppm	ASTM D5185m	>30	**19**	15	9
Copper	ppm	ASTM D5185m	>150	**2**	2	2
Tin	ppm	ASTM D5185m	>5	**3**	2	<1
Vanadium	ppm	ASTM D5185m		**0**	0	<1
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	**2**	1	18
Barium	ppm	ASTM D5185m	0	**0**	<1	0
Molybdenum	ppm	ASTM D5185m	60	**52**	60	62
Manganese	ppm	ASTM D5185m	0	**<1**	1	<1
Magnesium	ppm	ASTM D5185m	1010	**879**	933	898
Calcium	ppm	ASTM D5185m	1070	**984**	1008	1078
Phosphorus	ppm	ASTM D5185m	1150	**975**	979	908
Zinc	ppm	ASTM D5185m	1270	**1167**	1163	1138
Sulfur	ppm	ASTM D5185m	2060	**3167**	3218	3054

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	**8**	6	5
Sodium	ppm	ASTM D5185m		**3**	3	▲ 222
Potassium	ppm	ASTM D5185m	>20	**2**	0	▲ 55
Fuel	%	ASTM D3524	>5	▲ **7.7**	▲ 6.1	<1.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	▲ **3**	2.1	5.1
Nitration	Abs/cm	*ASTM D7624	>20	**11.2**	10.1	13.3
Sulfation	Abs/.1mm	*ASTM D7415	>30	**25.8**	24.8	30.6

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	**18.1**	21.1	19.1
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	**6.2**	5.3	▲ 0.0

OIL DIAGNOSTICS

OIL ANALYSIS REPORT

Fuel Dilution



FT-IR (Direct Trend)



Soot %



Base Number



Viscosity @ 100°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	**13.0**	▲ 12.1	15.0

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 100°C



Base Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : PCA0117394
Lab Number : 06240099
Unique Number : 11128933
Test Package : FLEET (Additional Tests: PercentFuel)

Received : 18 Jul 2024
Tested : 22 Jul 2024
Diagnosed : 22 Jul 2024 - Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

A Truck Repair
9349 China Grove Church Road
Pineville, NC
US 28134
Contact: Vlad Melnichuk
shop@migway.com
T: (980)255-3200
F:

Report Id: ATRPIN [WUSCAR] 06240099 (Generated: 07/22/2024 22:10:52) Rev: 3

Submitted By: Vlad Melnichuk