PROBLEM SUMMARY

Sample Rating Trend



VISUAL METAL

Area
PLANT 5
Machine Id
BAY 15 PACKAGING LINE
Component
1 Hydraulic System
Fluid
COMMERCIAL OIL LUBRIKO AW 46 (500 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

PROBLEMATIC TEST RESULTS

Sample Status				**ABNORMAL**	NORMAL	---
Particles >4µm		ASTM D7647	>5000	▲ **27972**	1800	---
Particles >6µm		ASTM D7647	>1300	▲ **1952**	113	---
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **22/18/12**	18/14/10	---
White Metal	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
Debris	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
PrtFilter					*no image*	*no image*

Customer Id: TAYSTO
Sample No.: WC0754613
Lab Number: 02590018
Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	---	---	?	We recommend you service the filters on this component.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Alert	---	---	?	We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.
Information Required	---	---	?	Please specify the component make and model with your next sample.
Check Dirt Access	---	---	?	We advise that you check all areas where contaminants can enter the system.
Check For Visual Metal	---	---	?	We advise that you check for visible metal particles in the oil.

HISTORICAL DIAGNOSIS

NORMAL

28 Dec 2020 Diag: Wes Davis

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the component make and model with your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



VISUAL METAL

Area
PLANT 5
Machine Id
BAY 15 PACKAGING LINE
Component
1 Hydraulic System
Fluid
COMMERCIAL OIL LUBRIKO AW 46 (500 LTR)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique.
DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

Wear

Light concentration of visible metal present.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Particle Filter (Magn: 100 x)



SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0754613**	WC	---
Sample Date		Client Info		**01 Oct 2023**	28 Dec 2020	---
Machine Age	hrs	Client Info		**0**	0	---
Oil Age	hrs	Client Info		**0**	0	---
Oil Changed		Client Info		**Not Changd**	N/A	---
Sample Status				**ABNORMAL**	NORMAL	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	**1**	<1	---
Chromium	ppm	ASTM D5185(m)	>10	**0**	0	---
Nickel	ppm	ASTM D5185(m)	>10	**<1**	<1	---
Titanium	ppm	ASTM D5185(m)		**0**	0	---
Silver	ppm	ASTM D5185(m)		**<1**	<1	---
Aluminum	ppm	ASTM D5185(m)	>10	**0**	<1	---
Lead	ppm	ASTM D5185(m)	>10	**<1**	1	---
Copper	ppm	ASTM D5185(m)	>75	**5**	6	---
Tin	ppm	ASTM D5185(m)	>10	**0**	<1	---
Antimony	ppm	ASTM D5185(m)		**0**	<1	---
Vanadium	ppm	ASTM D5185(m)		**0**	0	---
Beryllium	ppm	ASTM D5185(m)		**0**	0	---
Cadmium	ppm	ASTM D5185(m)		**0**	0	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**1**	2	---
Barium	ppm	ASTM D5185(m)		**<1**	<1	---
Molybdenum	ppm	ASTM D5185(m)		**<1**	<1	---
Manganese	ppm	ASTM D5185(m)		**0**	0	---
Magnesium	ppm	ASTM D5185(m)		**9**	9	---
Calcium	ppm	ASTM D5185(m)		**77**	110	---
Phosphorus	ppm	ASTM D5185(m)		**293**	337	---
Zinc	ppm	ASTM D5185(m)		**375**	443	---
Sulfur	ppm	ASTM D5185(m)		**1483**	2564	---
Lithium	ppm	ASTM D5185(m)		**<1**	<1	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>20	**<1**	1	---
Sodium	ppm	ASTM D5185(m)		**<1**	1	---
Potassium	ppm	ASTM D5185(m)	>20	**0**	<1	---

FLUID CLEANLINESS		method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	▲ **27972**	1800	---
Particles >6µm		ASTM D7647	>1300	▲ **1952**	113	---
Particles >14µm		ASTM D7647	>160	**22**	10	---
Particles >21µm		ASTM D7647	>40	**9**	4	---
Particles >38µm		ASTM D7647	>10	**1**	0	---
Particles >71µm		ASTM D7647	>3	**0**	0	---
Oil Cleanliness		ISO 4406 (c)	>19/17/14	▲ **22/18/12**	18/14/10	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		**0.56**	0.62	---

OIL ANALYSIS REPORT

Particle Count



Particle Trend



Acid Number



Viscosity @ 40°C



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
Yellow Metal	scalar	Visual*	NONE	**VLITE**	NONE	---
Precipitate	scalar	Visual*	NONE	**NONE**	NONE	---
Silt	scalar	Visual*	NONE	**VLITE**	NONE	---
Debris	scalar	Visual*	NONE	▲ **LIGHT**	NONE	---
Sand/Dirt	scalar	Visual*	NONE	**NONE**	NONE	---
Appearance	scalar	Visual*	NORML	**NORML**	NORML	---
Odor	scalar	Visual*	NORML	**NORML**	NORML	---
Emulsified Water	scalar	Visual*	>0.1	**NEG**	NEG	---
Free Water	scalar	Visual*		**NEG**	NEG	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46	**42.3**	44.3	---

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color					*no image*
Bottom					*no image*
PrtFilter				*no image*	*no image*

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C



Particle Filter (Magn: 100 x)



Acid Number



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0754613 **Received** : 18 Oct 2023
Lab Number : 02590018 **Diagnosed** : 20 Oct 2023
Unique Number : 5659084 **Diagnostician** : Kevin Marson
Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PrtFilter)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

TAYLOR STEEL
484 ARVIN AVE
STONEY CREEK, ON
CA L8E 2M9
Contact: George Campanaro
gcampanaro@taylorsteel.com
T: (905)662-4925
F: (905)662-4928

Report Id: TAYSTO [WCAMIS] 02590018 (Generated: 10/20/2023 14:43:06) Rev: 1

Submitted By: Matthew Fischer