OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
NEW FLYER 0905
Component
Diesel Engine
Fluid
SAFETY-KLEEN PERFORMANCE PLUS XHD-7 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0849888**	WC0849756	WC0849694
Sample Date		Client Info		**08 Dec 2023**	25 Oct 2023	11 Sep 2023
Machine Age	kms	Client Info		**1120323**	1110446	109943
Oil Age	kms	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**SEVERE**	SEVERE	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>75	**37**	49	26
Chromium	ppm	ASTM D5185(m)	>5	**1**	1	<1
Nickel	ppm	ASTM D5185(m)	>4	**0**	0	0
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**<1**	<1	0
Aluminum	ppm	ASTM D5185(m)	>15	**1**	1	<1
Lead	ppm	ASTM D5185(m)	>25	**<1**	<1	<1
Copper	ppm	ASTM D5185(m)	>100	**<1**	1	<1
Tin	ppm	ASTM D5185(m)	>4	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**1**	2	<1
Barium	ppm	ASTM D5185(m)		**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)		**59**	67	58
Manganese	ppm	ASTM D5185(m)		**0**	<1	<1
Magnesium	ppm	ASTM D5185(m)		**933**	1048	889
Calcium	ppm	ASTM D5185(m)		**1006**	1138	960
Phosphorus	ppm	ASTM D5185(m)		**923**	1019	929
Zinc	ppm	ASTM D5185(m)		**1134**	1265	1068
Sulfur	ppm	ASTM D5185(m)		**2286**	2526	2273
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**5**	8	4
Sodium	ppm	ASTM D5185(m)		**14**	18	24
Potassium	ppm	ASTM D5185(m)	>20	**10**	13	22
Fuel	%	ASTM D7593*	>3.0	**6**	8.6	6.7
Glycol	%	ASTM D7922*		**0.0**	0.0	0.0

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	**0.5**	0.7	0.6
Nitration	Abs/cm	ASTM D7624*	>20	**11.7**	12.7	11.2
Sulfation	Abs/.1mm	ASTM D7415*	>30	**25.3**	27.9	24.8

OIL ANALYSIS REPORT

Glycol Contamination



Viscosity @ 100°C



Glycol Contamination



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**27.7**	31.3	25.8

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.7	▲ **12.2**	▲ 12.3	▲ 12.4

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0849888 **Received** : 12 Dec 2023
Lab Number : 02602533 **Diagnosed** : 13 Dec 2023
Unique Number : 5695618 **Diagnostician** : Kevin Marson
Test Package : MOB 1 (Additional Tests: Glycol, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

CITY OF HAMILTON
2200 UPPER JAMES,, MOUNTAIN TRANSIT STOREROOM
MOUNT HOPE, ON
CA L0R 1W0
Contact: Jeff Parr
jeff.parr@hamilton.ca
T: (905)546-2424
F: (905)679-4502