OIL ANALYSIS REPORT

Sample Rating Trend

WATER

Machine Id
2277
Component
Natural Gas Engine
Fluid
VALVOLINE PREMIUM BLUE 9200 15W40 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is a moderate concentration of water present in the oil. Test for glycol is negative.

Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0891023**	---	---
Sample Date		Client Info		**17 Jan 2024**	---	---
Machine Age	kms	Client Info		**4095**	---	---
Oil Age	kms	Client Info		**0**	---	---
Oil Changed		Client Info		**N/A**	---	---
Sample Status				**ABNORMAL**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>50	**34**	---	---
Chromium	ppm	ASTM D5185(m)	>4	**<1**	---	---
Nickel	ppm	ASTM D5185(m)	>2	**<1**	---	---
Titanium	ppm	ASTM D5185(m)		**0**	---	---
Silver	ppm	ASTM D5185(m)	>3	**0**	---	---
Aluminum	ppm	ASTM D5185(m)	>9	**2**	---	---
Lead	ppm	ASTM D5185(m)	>30	**1**	---	---
Copper	ppm	ASTM D5185(m)	>35	**16**	---	---
Tin	ppm	ASTM D5185(m)	>4	**<1**	---	---
Antimony	ppm	ASTM D5185(m)		**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**29**	---	---
Barium	ppm	ASTM D5185(m)		**2**	---	---
Molybdenum	ppm	ASTM D5185(m)		**50**	---	---
Manganese	ppm	ASTM D5185(m)		**11**	---	---
Magnesium	ppm	ASTM D5185(m)		**742**	---	---
Calcium	ppm	ASTM D5185(m)		**1166**	---	---
Phosphorus	ppm	ASTM D5185(m)		**729**	---	---
Zinc	ppm	ASTM D5185(m)		**817**	---	---
Sulfur	ppm	ASTM D5185(m)		**2109**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>+100	**36**	---	---
Sodium	ppm	ASTM D5185(m)		**5**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**2**	---	---
Water	%	ASTM D6304*	>0.1	▲ **0.182**	---	---
ppm Water	ppm	ASTM D6304*	>1000	▲ **1829**	---	---
Glycol	%	ASTM D7922*		**0.0**	---	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*		**0**	---	---
Nitration	Abs/cm	ASTM D7624*	>20	**9.3**	---	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	**20.3**	---	---

FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**18.0**	---	---

OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.1	▲ .2%	---	---
Free Water	scalar	Visual*		NEG	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	14.8	**13.8**	---	---

GRAPHS























ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0891023 **Recieved** : 22 Jan 2024
Lab Number : 02610264 **Diagnosed** : 23 Jan 2024
Unique Number : 5711350 **Diagnostician** : Kevin Marson
Test Package : MOB 1 (Additional Tests: Glycol, KF)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

CITY OF HAMILTON
2200 UPPER JAMES,, MOUNTAIN TRANSIT STOREROOM
MOUNT HOPE, ON
CA L0R 1W0
Contact: Jeff Parr
jeff.parr@hamilton.ca
T: (905)546-2424
F: (905)679-4502