OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Machine Id
NEW FLYER 1015
Component
Diesel Engine
Fluid
SAFETY-KLEEN PERFORMANCE PLUS XHD-7 15W40 (--- GAL)

DIAGNOSIS

Recommendation
No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear
All component wear rates are normal.

Contamination
Light fuel dilution occurring. No other contaminants were detected in the oil.

Fluid Condition
The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0937260**	WC0890912	WC0878109
Sample Date		Client Info		**09 Jun 2024**	23 Jan 2024	07 Dec 2023
Machine Age	kms	Client Info		**1047395**	1045578	0
Oil Age	kms	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	N/A	N/A
Sample Status				**MARGINAL**	SEVERE	SEVERE

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG
Glycol		WC Method		**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>75	**4**	14	12
Chromium	ppm	ASTM D5185(m)	>5	**0**	<1	<1
Nickel	ppm	ASTM D5185(m)	>4	**0**	<1	<1
Titanium	ppm	ASTM D5185(m)	>2	**0**	0	0
Silver	ppm	ASTM D5185(m)	>2	**0**	0	<1
Aluminum	ppm	ASTM D5185(m)	>15	**1**	2	1
Lead	ppm	ASTM D5185(m)	>25	**0**	<1	<1
Copper	ppm	ASTM D5185(m)	>100	**<1**	<1	<1
Tin	ppm	ASTM D5185(m)	>4	**0**	0	0
Antimony	ppm	ASTM D5185(m)		**0**	0	0
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Beryllium	ppm	ASTM D5185(m)		**0**	0	0
Cadmium	ppm	ASTM D5185(m)		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		**1**	<1	<1
Barium	ppm	ASTM D5185(m)		**0**	0	<1
Molybdenum	ppm	ASTM D5185(m)		**56**	57	55
Manganese	ppm	ASTM D5185(m)		**0**	0	0
Magnesium	ppm	ASTM D5185(m)		**927**	920	889
Calcium	ppm	ASTM D5185(m)		**941**	1000	963
Phosphorus	ppm	ASTM D5185(m)		**973**	959	913
Zinc	ppm	ASTM D5185(m)		**1128**	1128	1096
Sulfur	ppm	ASTM D5185(m)		**2508**	2566	2325
Lithium	ppm	ASTM D5185(m)		**<1**	<1	<1

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**2**	3	3
Sodium	ppm	ASTM D5185(m)		**1**	1	2
Potassium	ppm	ASTM D5185(m)	>20	**0**	<1	0
Fuel	%	ASTM D7593*	>3.0	▲ **2**	▲ 7.2	▲ 7.2

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>6	**0**	0.2	0.2
Nitration	Abs/cm	ASTM D7624*	>20	**5.6**	10.1	9.3
Sulfation	Abs/.1mm	ASTM D7415*	>30	**18.1**	21.3	21.4

OIL ANALYSIS REPORT

FT-IR (Direct Trend)



FT-IR (Direct Trend)



Viscosity @ 100°C



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**13.6**	20.5	21.3

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	NEG	NEG
Free Water	scalar	Visual*		**NEG**	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.7	**14.0**	▲ 11.9	▲ 11.6

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



▲ Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0937260 **Received** : 12 Jun 2024
Lab Number : 02641353 **Tested** : 13 Jun 2024
Unique Number : 5798892 **Diagnosed** : 13 Jun 2024 - Wes Davis
Test Package : MOB 1 (Additional Tests: PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

CITY OF HAMILTON
2200 UPPER JAMES,, MOUNTAIN TRANSIT STOREROOM
MOUNT HOPE, ON
CA L0R 1W0
Contact: Jeff Parr
jeff.parr@hamilton.ca
T: (905)546-2424
F: (905)679-4502