PROBLEM SUMMARY

Sample Rating Trend



FUEL

Area
ORIN CONTRACTORS
Machine Id
384
Component
Diesel Engine
Fluid
DIESEL ENGINE OIL SAE 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				**SEVERE**	---	---
Calcium	ppm	ASTM D5185(m)	3000	▲ **877**	---	---
Fuel	%	ASTM D7593*	>5	▲ **12.4**	---	---
Visc @ 100°C	cSt	ASTM D7279(m)	14.4	▲ **8.8**	---	---

Customer Id: RONVAU
Sample No.: WC0932657
Lab Number: 02646951
Test Package: MOBCE

To manage this report scan the QR code

To discuss the diagnosis or test data:
Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS

OIL ANALYSIS REPORT

Sample Rating Trend



FUEL

Area
ORIN CONTRACTORS
Machine Id
384
Component
Diesel Engine
Fluid
DIESEL ENGINE OIL SAE 15W40 (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
All component wear rates are normal.

Contamination
There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.

Fluid Condition
Visc @ 100°C is severely low. Calcium ppm levels are abnormally low. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0932657**	---	---
Sample Date		Client Info		**15 Jun 2024**	---	---
Machine Age	hrs	Client Info		**0**	---	---
Oil Age	hrs	Client Info		**0**	---	---
Oil Changed		Client Info		**Changed**	---	---
Sample Status				**SEVERE**	---	---

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	---	---
Glycol		WC Method		**NEG**	---	---

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	**19**	---	---
Chromium	ppm	ASTM D5185(m)	>20	**1**	---	---
Nickel	ppm	ASTM D5185(m)	>4	**<1**	---	---
Titanium	ppm	ASTM D5185(m)		**0**	---	---
Silver	ppm	ASTM D5185(m)	>3	**0**	---	---
Aluminum	ppm	ASTM D5185(m)	>20	**3**	---	---
Lead	ppm	ASTM D5185(m)	>40	**26**	---	---
Copper	ppm	ASTM D5185(m)	>330	**2**	---	---
Tin	ppm	ASTM D5185(m)	>15	**<1**	---	---
Antimony	ppm	ASTM D5185(m)		**0**	---	---
Vanadium	ppm	ASTM D5185(m)		**0**	---	---
Beryllium	ppm	ASTM D5185(m)		**0**	---	---
Cadmium	ppm	ASTM D5185(m)		**0**	---	---

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	250	**1**	---	---
Barium	ppm	ASTM D5185(m)	10	**<1**	---	---
Molybdenum	ppm	ASTM D5185(m)	100	**52**	---	---
Manganese	ppm	ASTM D5185(m)		**<1**	---	---
Magnesium	ppm	ASTM D5185(m)	450	**826**	---	---
Calcium	ppm	ASTM D5185(m)	3000	▲ **877**	---	---
Phosphorus	ppm	ASTM D5185(m)	1150	**841**	---	---
Zinc	ppm	ASTM D5185(m)	1350	**1021**	---	---
Sulfur	ppm	ASTM D5185(m)	4250	**2190**	---	---
Lithium	ppm	ASTM D5185(m)		**<1**	---	---

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	**4**	---	---
Sodium	ppm	ASTM D5185(m)	>158	**2**	---	---
Potassium	ppm	ASTM D5185(m)	>20	**1**	---	---
Fuel	%	ASTM D7593*	>5	▲ **12.4**	---	---

INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	**0.4**	---	---
Nitration	Abs/cm	ASTM D7624*	>20	**11.3**	---	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	**19.6**	---	---

OIL ANALYSIS REPORT

Additives



FT-IR (Direct Trend)



Additives



FT-IR (Direct Trend)



FLUID DEGRADATION		method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	**19.0**	---	---

VISUAL		method	limit/base	current	history1	history2
Emulsified Water	scalar	Visual*	>0.2	**NEG**	---	---
Free Water	scalar	Visual*		**NEG**	---	---

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	14.4	▲ **8.8**	---	---

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



▲ Viscosity @ 100°C



▲ Fuel Dilution



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0932657
Lab Number : 02646951
Unique Number : 5812503
Test Package : MOBCE (Additional Tests: FuelDilution, PercentFuel)

Received : 10 Jul 2024
Tested : 11 Jul 2024
Diagnosed : 11 Jul 2024 - Wes Davis

RONI/IRON SHORE EXCAVATING LTD.
100 MACINTOSH BLVD
VAUGHAN, ON
CA L4K 4P3
Contact: Service Team
service.team@roni.ca
T:
F:

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.