OIL ANALYSIS REPORT

Sample Rating Trend



WEAR

Machine Id
2 ID IB MOTOR
Component
Bearing
Fluid
CHEVRON RANDO HD 68 (--- QTS)

DIAGNOSIS

Recommendation
We recommend an early resample to monitor this condition.

Wear
The iron level is abnormal. Bearing and/or bushing wear is indicated.

Contamination
There is no indication of any contamination in the oil.

Fluid Condition
The AN level is acceptable for this fluid.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0722114**	WC0346600	WC0346596
Sample Date		Client Info		**27 Sep 2023**	14 Jul 2022	15 Jul 2020
Machine Age	mths	Client Info		**0**	32	8
Oil Age	mths	Client Info		**0**	1	0
Oil Changed		Client Info		**N/A**	Changed	Changed
Sample Status				**ABNORMAL**	NORMAL	NORMAL

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	▲ **277**	<1	<1
Chromium	ppm	ASTM D5185m	>5	**2**	0	0
Nickel	ppm	ASTM D5185m	>5	**0**	0	<1
Titanium	ppm	ASTM D5185m	>5	**<1**	0	0
Silver	ppm	ASTM D5185m		**0**	2	0
Aluminum	ppm	ASTM D5185m	>25	**<1**	<1	0
Lead	ppm	ASTM D5185m	>50	**21**	2	2
Copper	ppm	ASTM D5185m	>150	▲ **108**	35	27
Tin	ppm	ASTM D5185m	>10	▲ **29**	<1	0
Antimony	ppm	ASTM D5185m		**---**	---	0
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**<1**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**0**	<1	0
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**<1**	<1	0
Manganese	ppm	ASTM D5185m		**5**	0	0
Magnesium	ppm	ASTM D5185m		**0**	0	<1
Calcium	ppm	ASTM D5185m		**39**	56	78
Phosphorus	ppm	ASTM D5185m		**340**	363	323
Zinc	ppm	ASTM D5185m		**401**	446	398
Sulfur	ppm	ASTM D5185m		**862**	1055	1124

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	**10**	1	2
Sodium	ppm	ASTM D5185m		**4**	0	2
Potassium	ppm	ASTM D5185m	>20	**2**	0	0

FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		**0.26**	0.28	0.309

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	VLITE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Debris	scalar	*Visual	NONE	**LIGHT**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	**NEG**	NEG	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT

Ferrous Alloys



Non-ferrous Metals



Acid Number



Viscosity @ 40°C



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	64.6	**66.53**	70.2	67.6

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS

Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Acid Number



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0722114
Lab Number : 05966480
Unique Number : 10673031
Test Package : MOB 2

Received : 02 Oct 2023
Diagnosed : 06 Oct 2023
Diagnostician : Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T.E.S. FILER CITY STATION
700 MEE ST.
FILER CITY, MI
US 49634
Contact: CLARK JOHNSON
clark.johnson@cmsenergy.com
T: (231)723-6573
F: (231)723-6630