PROBLEM SUMMARY

Sample Rating Trend



DIRT

Machine Id
CATERPILLAR D6 10033 (S/N KEW01101)
Component
Left Final Drive
Fluid
{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				SEVERE	SEVERE	NORMAL
Chromium	ppm	ASTM D5185m	>10	▲ **13**	▲ 16	2
Silicon	ppm	ASTM D5185m	>75	▲ **362**	▲ 246	27

Customer Id: TRANEW
Sample No.: WC0888217
Lab Number: 06131171
Test Package: CONST

To manage this report scan the QR code

To discuss the diagnosis or test data:
Don Baldridge +1
don.b505@comcast.net

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Dirt Access	---	---	?	We advise that you check all areas where dirt can enter the system.

HISTORICAL DIAGNOSIS

14 Dec 2023 Diag: Don Baldridge

DIRT

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.The chromium level is abnormal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

view report

21 Sep 2023 Diag: Don Baldridge

NORMAL

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

view report

13 Jul 2023 Diag: Sean Felton

NORMAL

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

view report

OIL ANALYSIS REPORT

Sample Rating Trend



DIRT

Machine Id
CATERPILLAR D6 10033 (S/N KEW01101)
Component
Left Final Drive
Fluid
{not provided} (--- GAL)

DIAGNOSIS

Recommendation
We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear
The chromium level is abnormal.

Contamination
Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.

Fluid Condition
The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number		Client Info		**WC0888217**	WC0879267	WC0831354
Sample Date		Client Info		**20 Mar 2024**	14 Dec 2023	21 Sep 2023
Machine Age	hrs	Client Info		**5480**	4709	4241
Oil Age	hrs	Client Info		**771**	468	468
Oil Changed		Client Info		**Changed**	Changed	Changed
Sample Status				**SEVERE**	SEVERE	NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	**NEG**	NEG	NEG

WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	**205**	165	24
Chromium	ppm	ASTM D5185m	>10	▲ **13**	▲ 16	2
Nickel	ppm	ASTM D5185m	>10	**3**	3	1
Titanium	ppm	ASTM D5185m		**2**	2	<1
Silver	ppm	ASTM D5185m		**0**	0	0
Aluminum	ppm	ASTM D5185m	>25	● **18**	● 16	3
Lead	ppm	ASTM D5185m	>25	**0**	0	0
Copper	ppm	ASTM D5185m	>50	**<1**	0	5
Tin	ppm	ASTM D5185m	>10	**0**	0	<1
Vanadium	ppm	ASTM D5185m		**0**	0	0
Cadmium	ppm	ASTM D5185m		**0**	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		**146**	149	158
Barium	ppm	ASTM D5185m		**0**	0	0
Molybdenum	ppm	ASTM D5185m		**2**	1	<1
Manganese	ppm	ASTM D5185m		**3**	3	<1
Magnesium	ppm	ASTM D5185m		**0**	<1	2
Calcium	ppm	ASTM D5185m		**106**	49	102
Phosphorus	ppm	ASTM D5185m		**328**	271	312
Zinc	ppm	ASTM D5185m		**18**	6	24
Sulfur	ppm	ASTM D5185m		**2070**	1914	2143

CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	▲ **362**	▲ 246	27
Sodium	ppm	ASTM D5185m		**3**	0	0
Potassium	ppm	ASTM D5185m	>20	**4**	6	2

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	**NONE**	NONE	NONE
Precipitate	scalar	*Visual	NONE	**NONE**	NONE	NONE
Silt	scalar	*Visual	NONE	**MODER**	MODER	NONE
Debris	scalar	*Visual	NONE	**NONE**	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	**NONE**	NONE	NONE
Appearance	scalar	*Visual	NORML	**NORML**	NORML	NORML
Odor	scalar	*Visual	NORML	**NORML**	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	**NEG**	0.2%	NEG
Free Water	scalar	*Visual		**NEG**	NEG	NEG

OIL ANALYSIS REPORT

Silicon (ppm)



Aluminum (ppm)



Aluminum (ppm)



Viscosity @ 40°C



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		**104**	101	84.8

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			*no image*	*no image*	*no image*
Bottom			*no image*	*no image*	*no image*

GRAPHS

Ferrous Alloys



Non-ferrous Metals



Viscosity @ 40°C



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0888217
Lab Number : 06131171
Unique Number : 10950636
Test Package : CONST

Received : 27 Mar 2024
Tested : 28 Mar 2024
Diagnosed : 01 Apr 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.
** - Denotes test methods that are outside of the ISO 17025 scope of accreditation.*
Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

TRADER CONSTRUCTION CO.
PO DRAWER 1578
NEW BERN, NC
US 28563
Contact: MIKE WYATT
mwyatt@traderconstruction.com
T: (252)633-1399
F: (252)638-4871