OIL ANALYSIS REPORT

VOLVO PENTA

ZF 20005191 - STARBOARD TRANSMISSION

Sample No: VPA049539

Oil Type: SAE 30W

SAMPLE INFORMATION

Sample Number		**VPA049539**	---	---	---
Sample Date		**09 May 2024**	---	---	---
Machine Hours		**0**	---	---	---
Oil Hours		**0**	---	---	---
Oil Changed		**N/A**	---	---	---
Sample Status		**NORMAL**	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	**92.1**	---	---	---

CONTAMINATION

Water	%	**NEG**	---	---	---
Silicon	ppm	**12**	---	---	---
Sodium	ppm	**2**	---	---	---
Potassium	ppm	**0**	---	---	---

WEAR METALS

PQ		**41**	---	---	---
Iron	ppm	**32**	---	---	---
Copper	ppm	**52**	---	---	---
Lead	ppm	**0**	---	---	---
Tin	ppm	**<1**	---	---	---
Aluminum	ppm	**8**	---	---	---
Chromium	ppm	**0**	---	---	---
Molybdenum	ppm	**50**	---	---	---
Nickel	ppm	**0**	---	---	---
Titanium	ppm	**0**	---	---	---
Silver	ppm	**0**	---	---	---
Manganese	ppm	**<1**	---	---	---
Vanadium	ppm	**0**	---	---	---

ADDITIVES

Calcium	ppm	**3754**	---	---	---
Magnesium	ppm	**0**	---	---	---
Zinc	ppm	**1208**	---	---	---
Phosphorus	ppm	**1109**	---	---	---
Barium	ppm	**0**	---	---	---
Boron	ppm	**528**	---	---	---

MYRIAD MARINE
2 CIVIC CENTER DR, SUITE 4112
SAN RAFEAL, CA
US 94903
Contact: SEAN CORBETT
sean@myriadmarine.com
T:
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VPMYRSAN
Unique No: 11034498
Signed: Sean Felton
Report Date: 21 May 2024

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

Iron (ppm)

Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



PQ