



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL


Machine Id
183
 Component
Rear Transmission (Auto)
 Fluid

RECOMMENDATION


Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC00011629	---	---
Sample Date		Client Info		13 Aug 1990	---	---
Machine Age	kms	Client Info		180897	---	---
Oil Age	kms	Client Info		48000	---	---
Filter Age	kms	Client Info		48000	---	---
Sample Status				---	---	---
Water		WC Method		NEG	---	---

WEAR


Iron (ppm)




Lead (ppm)




Aluminum (ppm)




Chromium (ppm)




Copper (ppm)




Silicon (ppm)



Viscosity @ 40°C



Additives



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC00011629
Lab Number : 00057755
Unique Number : 24237
Test Package : MOB 1

CITY OF THUNDER BAY
 AUTO MAINTENANCE STORES, 570 FORT WILLIAM ROAD
 THUNDER BAY, ON
 CA P7B 2Z8
 Contact: Sean Malcolm
 sean.malcolm@thunderbay.ca
 T: (807)684-2716
 F: (807)344-0237

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.