**WEAR CONTAMINATION FLUID CONDITION** 

**NORMAL NORMAL NORMAL** 

## LKQ CANADA AUTO PARTS INC [390106]

**VOLVO L90H 623925** 

Front Axle

Fluid VOLVO WB 102 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP394172		
	Sample Date		Client Info		05 Jan 2024		
	Machine Age	hrs	Client Info		11982		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>300	9		
All component wear rates are normal.	Chromium	ppm	ASTM D5185(m)	>10	0		
	Nickel	ppm	ASTM D5185(m)		<1		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>15	2		
	Lead	ppm	ASTM D5185(m)	>4	0		
	Copper	ppm	ASTM D5185(m)	>200	<1		
	Tin	ppm	ASTM D5185(m)	>15	0		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>75	17		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	<1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	LIGHT		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)		115		
	Barium	ppm	ASTM D5185(m)		0		
	Molybdenum	ppm	ASTM D5185(m)		0		
	Manganese	ppm	ASTM D5185(m)		0		
	Magnesium	ppm	ASTM D5185(m)		13		
	Calcium	ppm	ASTM D5185(m)		4164		
	Phosphorus	ppm	ASTM D5185(m)		1328		
	Zinc	ppm	ASTM D5185(m)		1654		
	Sulfur	ppm	ASTM D5185(m)		3448		
	Visc @ 40°C	cSt	ASTM D7279(m)		42.4		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number : 02607220 Unique Number : 5708306 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : VCP394172 Recieved : 08 Jan 2024 : 08 Jan 2024 Diagnosed Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD MISSISSAUGA, ON CA L4W 4L4

Contact: Jamal Harvey jharvey@strongco.com

F: (905)670-2338