

WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL



VOLVO ECR145E 316243

Component Front Left Final Drive

VOLVO API GL-5 SAE 75W90 (GAL)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP335154		
	Sample Date		Client Info		20 Dec 2023		
	Machine Age	hrs	Client Info		951		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>500	246		
Metal levels are typical for a new component breaking in.	Chromium	ppm	ASTM D5185(m)	>10	4		
	Nickel	ppm	ASTM D5185(m)	>10	<1		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver	ppm	ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>25	2		
	Lead	ppm	ASTM D5185(m)	>25	0		
	Copper	ppm	ASTM D5185(m)	>50	<1		
	Tin	ppm	ASTM D5185(m)	>10	13		
	Vanadium	ppm	ASTM D5185(m)		0		
	White Metal	scalar	Visual*	NONE	VLITE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>75	10		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	1		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185(m)		4		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185(m)		106		
	Barium	ppm	ASTM D5185(m)		<1		
	Molybdenum	ppm	ASTM D5185(m)		0		
	Manganese	ppm	ASTM D5185(m)		3		
	Magnesium	ppm	ASTM D5185(m)		<1		
	Calcium	ppm	ASTM D5185(m)		16		
	Phosphorus	ppm	ASTM D5185(m)		932		
	Zinc	ppm	ASTM D5185(m)		22		
	Sulfur	ppm	ASTM D5185(m)		23538		
	Visc @ 40°C	cSt	ASTM D7279(m)		131		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number

: VCP335154 : 02607579 : 5708665 **Unique Number** Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved : 09 Jan 2024 Diagnosed : 09 Jan 2024 Diagnostician : Kevin Marson

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

CITY OF KELOWNA 1435 WATER STREET

KELOWNA, BC **CA V1Y 1J4** Contact: Myles Bancarz

mbancarz@kelowna.ca T: (250)763-6011 F: (250)868-3330