



Machine Id
713069

Component
Hydraulic System

Fluid
PETRO CANADA HYDREX MV 32 (--- GAL)

RECOMMENDATION

Vérifier les scelles et/ou les filtres pour des points d'entrée des contaminants. Le reniflard d'air doit être réparé. S'il n'est pas classé, nous vous recommandons de le remplacer par un reniflard à air adapté au micron et / ou au dessiccant. Si évalué, nous vous recommandons de réparer / remplacer le reniflard. Nous avons pris note que le filtre a été remplacé au moment de l'échantillonnage. Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau dans 30 à 45 jours afin de contrôler la situation.

WEAR

Les taux d'usure de tous les composants sont normaux.









CONTAMINATION

Il y a une grande quantité de limon (particules de 4 à 14 microns) dans l'huile.

FLUID CONDITION

Les niveaux d'additifs indiquent l'ajout d'une autre marque ou d'un autre type d'huile. L'huile peut encore servir si la contamination peut être réduite à un niveau acceptable.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		GFL0103734	GFL0084448	---
Sample Date		Client Info		15 Jan 2024	10 Aug 2023	---
Machine Age	kms	Client Info		1850	9786	---
Oil Age	kms	Client Info		0	0	---
Filter Age	kms	Client Info		0	0	---
Oil Changed		Client Info		Not Changd	N/A	---
Filter Changed		Client Info		Changed	N/A	---
Sample Status				SEVERE	SEVERE	---
Iron	ppm	ASTM D5185(m)	>20	8	5	---
Chromium	ppm	ASTM D5185(m)	>10	0	0	---
Nickel	ppm	ASTM D5185(m)	>10	<1	<1	---
Titanium	ppm	ASTM D5185(m)		0	0	---
Silver	ppm	ASTM D5185(m)		0	0	---
Aluminum	ppm	ASTM D5185(m)	>10	<1	<1	---
Lead	ppm	ASTM D5185(m)	>10	<1	0	---
Copper	ppm	ASTM D5185(m)	>75	<1	<1	---
Tin	ppm	ASTM D5185(m)	>10	0	0	---
Vanadium	ppm	ASTM D5185(m)		0	0	---
White Metal	scalar	Visual*	NONE	NONE	NONE	---
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	---
Silicon	ppm	ASTM D5185(m)	>20	<1	<1	---
Potassium	ppm	ASTM D5185(m)	>20	3	<1	---
Water		WC Method	>0.1	NEG	NEG	---
Particles >4µm		ASTM D7647	>5000	107754	57914	---
Particles >6µm		ASTM D7647	>1300	22466	7455	---
Particles >14µm		ASTM D7647	>160	268	66	---
Particles >21µm		ASTM D7647	>40	24	14	---
Particles >38µm		ASTM D7647	>10	1	0	---
Particles >71µm		ASTM D7647	>3	1	0	---
Oil Cleanliness		ISO 4406 (c)	>19/17/14	24/22/15	23/20/13	---
Silt	scalar	Visual*	NONE	NONE	NONE	---
Debris	scalar	Visual*	NONE	NONE	NONE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	---
Appearance	scalar	Visual*	NORML	NORML	NORML	---
Odor	scalar	Visual*	NORML	NORML	NORML	---
Emulsified Water	scalar	Visual*	>0.1	NEG	NEG	---
Sodium	ppm	ASTM D5185(m)		3	1	---
Boron	ppm	ASTM D5185(m)	0	0	<1	---
Barium	ppm	ASTM D5185(m)	0	0	0	---
Molybdenum	ppm	ASTM D5185(m)	0	0	0	---
Manganese	ppm	ASTM D5185(m)	1	0	0	---
Magnesium	ppm	ASTM D5185(m)	0	2	2	---
Calcium	ppm	ASTM D5185(m)	50	368	498	---
Phosphorus	ppm	ASTM D5185(m)	330	236	235	---
Zinc	ppm	ASTM D5185(m)	430	173	130	---
Sulfur	ppm	ASTM D5185(m)	760	985	982	---
Visc @ 40°C	cSt	ASTM D7279(m)	31.9	31.7	31.8	---



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 GFL Environmental - 780 - GMA - ICI - Solid Waste
Sample No. : GFL0103734 **Received** : 18 Jan 2024 4365 boul. St-Elzear Ouest, Laval, QC
Lab Number : 02609711 **Diagnosed** : 19 Jan 2024 CA H7P 4J3
Unique Number : 5710797 **Diagnostician** : Wes Davis Contact: Louis Michaud
Test Package : MOB 1 (Additional Tests: PrtCount) louis.michaud@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.