

Area [14278] Machine Id TRAIL BULLY 2017 Component Diesel Fuel Fluid DIESEL FUEL No. 1 (--- GAL)

RECOMMENDATION

We recommend that you drain the fuel from the component if this has not already been done. We recommend an early resample to monitor this condition. Diagnostician's Note: Laboratory testing indicates the diesel fuel is contaminated with approximately 20% gasoline.

CORROSION

{not applicable}

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0667883		
Sample Date		Client Info		15 Feb 2024		
Machine Age	hrs	Client Info		0		
Sample Status				SEVERE		
Pensky-Martens Flash Point	°C	ASTM D7215*		• -26.2		
Initial Boiling Point	°C	ASTM D2887*	166	<mark>▲</mark> 53		
10% Distill Point	°C	ASTM D2887*	186	<mark> </mark> 85		
20% Distill Point	°C	ASTM D2887*	206	🔺 116		
30% Distill Point	°C	ASTM D2887*	226	140		
40% Distill Point	°C	ASTM D2887*	245	163		
50% Distill Point	°C	ASTM D2887*	260	A 186		
60% Distill Point	°C	ASTM D2887*	267	207		
70% Distill Point	°C	ASTM D2887*	275	228		
80% Distill Point	°C	ASTM D2887*	283	253		
90% Distill Point	°C	ASTM D2887*	290	282		
Final Boiling Point	°C	ASTM D2887*	315	A 330		
Cetane Index		ASTM D4737*	<40.0	47		



