

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL


(CFTJC) SKYCARE AIR AMBULANCE [53122]
Machine Id
[CFTJC] FAIRCHILD SA226 P-54224 (S/N TC-274)

1 Jet Turbine

EASTMAN TURBO OIL 2380 (--- GAL)

COMMENDATION								
NDATION		Test	UOM	Method	Limit/Abn	Current	History1	History2
		Sample Number		Client Info		GT57713	GT57716	GT57137
		Sample Date		Client Info		31 Mar 2024	14 Mar 2024	20 Feb 2024
		Machine Age	hrs	Client Info		0	0	0
		Oil Age	hrs	Client Info		144	66	723
		Filter Age	hrs	Client Info		77	67	65
		Oil Changed		Client Info		N/A	N/A	N/A
		Filter Changed		Client Info		N/A	N/A	N/A
		Sample Status						
		Iron	ppm	ASTM D5185(m)	>8	0	0	<1
		Chromium	ppm	ASTM D5185(m)	>2	0	0	0
		Nickel	ppm	ASTM D5185(m)	>2	0	0	0
		Silver	ppm	ASTM D5185(m)	>2	0	0	0
		Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	1
	Lead	ppm	ASTM D5185(m)	>3	<1	<1	<1	
		Copper	ppm	ASTM D5185(m)	>3	0	0	0
		Water		WC Method	>0.1	NEG	NEG	NEG
		Magnesium	ppm	ASTM D5185(m)	0	0	0	0
		Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.49	0.54	0.55
		Visc @ 40°C	cSt	ASTM D7279(m)	24.2			







CALA ISO 17025:2017 Accredited Laboratory

Unique Number : 5759431

Laboratory Sample No.

: GT57713 Lab Number : 02626299

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received

: 02 Apr 2024 Tested Diagnosed Test Package : G331 (Additional Tests: ICP)

Honeywell Engines 111 S. 34th Street, 301 Receiving, Attn: SOAP Program

PHOENIX, AZ US 85034 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (602)365-2676

Contact/Location: GARRETT? - HONPHO

T: