

**OIL ANALYSIS REPORT** 

WEAR CONTAMINATION FLUID CONDITION

UNKNOWN UNKNOWN


Area

## (CGIQG) PERIMETER AVIATION [53133] [CGIQG] FAIRCHILD SA226TC P54093 (S/N TC288)

1 Jet Turbine

EASTMAN TURBO OIL 2380 (--- GAL)

DATION		Test	UOM	Method	Limit/Abn	Current	History1	History2
		Sample Number		Client Info		GT57284	GT57273	GT56331
		Sample Date		Client Info		28 Mar 2024	10 Jan 2024	09 Mar 2023
		Machine Age	hrs	Client Info		0	0	0
		Oil Age	hrs	Client Info		107	22	396
		Filter Age	hrs	Client Info		84	22	95
		Oil Changed		Client Info		N/A	N/A	N/A
		Filter Changed		Client Info		N/A	N/A	N/A
		Sample Status				<b></b>	NORMAL	
		Iron	ppm	ASTM D5185(m)	>8	0	0	<1
		Chromium	ppm	ASTM D5185(m)	>2	0	0	0
		Nickel	ppm	ASTM D5185(m)	>2	0	0	0
		Silver	ppm	ASTM D5185(m)	>2	0	0	0
		Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
		Lead	ppm	ASTM D5185(m)	>3	<1	0	0
		Copper	ppm	ASTM D5185(m)	>3	<1	<1	0
		Water		WC Method	>0.1	NEG	NEG	NEG
		Magnesium	ppm	ASTM D5185(m)	0	0	0	0
		Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.47	0.49	0.43
		Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.2	24.1	







Laboratory Sample No.

Lab Number : 02626507

: GT57284 Unique Number : 5759639

Received **Tested** Diagnosed

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 03 Apr 2024

111 S. 34th Street, 301 Receiving, Attn: SOAP Program PHOENIX, AZ US 85034 Contact: GARRETT

Test Package: G331 (Additional Tests: ICP) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676

**Honeywell Engines**