

# CONTAMINATION NORMAL

WEAR

**ABNORMAL** 

#### Machine Id BTV04 Component Transmission (Auto) Fluid MOBIL MOBILTRANS HD 30 (--- GAL)

### RECOMMENDATION

The fluid change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please specify the component make and model with your next sample.

#### **WEAR**

Lead ppm levels are abnormal. Clutch disc wear indicated.

#### CONTAMINATION


There is no indication of any contamination in the fluid.


## FLUID CONDITION

Additive levels indicate the addition of a different brand, or type of fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0925788		
Sample Date		Client Info		16 Apr 2024		
Machine Age	hrs	Client Info		11096		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Filter Changed		Client Info		Changed		
Sample Status				ABNORMAL		
lron			. 100	10		
Iron Chromium	ppm	ASTM D5185(m)	>160	10		
	ppm	ASTM D5185(m)	>5	0		
Nickel	ppm	ASTM D5185(m)	>5	0		
Titanium	ppm	ASTM D5185(m)	-	0		
Silver	ppm	ASTM D5185(m)	>5	0		
Aluminum	ppm	ASTM D5185(m)	>50	3		
Lead	ppm	ASTM D5185(m)	>50	▲ 159		
Copper	ppm	ASTM D5185(m)	>225	178		
Tin	ppm	ASTM D5185(m)	>10	0		
Vanadium	ppm	ASTM D5185(m)		0		
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Silicon	ppm	ASTM D5185(m)	>20	4		
Potassium	ppm	ASTM D5185(m)	>20	<1		
Water		WC Method	>0.1	NEG		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	VLITE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.1	NEG		
	ppm	ASTM D5185(m)				
Sodium		. ,		<1		
Boron	ppm	ASTM D5185(m)		15		
Boron Barium	ppm ppm	ASTM D5185(m) ASTM D5185(m)		15 0		
Boron Barium Molybdenum	ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0		
Boron Barium Molybdenum Manganese	ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0 <1		
Boron Barium Molybdenum Manganese Magnesium	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0 <1 115		
Boron Barium Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0 <1 115 2942		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0 <1 115 2942 858	  	
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 2 3 3 4 115 2942 858 858 897	  	
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)		15 0 0 <1 115 2942 858		   

Contact/Location: Mike Campbell - KIR370KIR





Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Agnico Eagle Canada CALA ■₿ Sample No. 1350 Government Rd. W, MACASSA COMPLEX : WC0925788 Received : 22 Apr 2024 Lab Number : 02630658 Tested : 23 Apr 2024 Kirkland Lake, ON ISO 17025:2017 Accredited Laboratory Unique Number : 5763790 : 23 Apr 2024 - Kevin Marson CA P2N 3J1 Diagnosed Test Package : MOB 1 Contact: Mike Campbell To discuss this sample report, contact Customer Service at 1-800-268-2131. mike.campbell@agnicoeagle.com T: (705)567-5208 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied. F: (705)567-5221

Contact/Location: Mike Campbell - KIR370KIR Page 2 of 2

pr16/24

[]