

**OIL ANALYSIS REPORT** 

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

Area


(BWQ) SKYCARE [53209]

[BWQ] FAIRCHILD SA226 P-54188 (S/N TC-379)

Right Jet Turbine

EASTMAN TURBO OIL 2380 (--- GAL)

	/							
RECOMMENDATION		Test	UOM	Method	Limit/Abn	Current	History1	History2
This is a baseline read-out on the submitted sa	sample.	Sample Number		Client Info		GT57709	GT57696	GT57707
		Sample Date		Client Info		22 Apr 2024	04 Apr 2024	20 Mar 2024
		Machine Age	hrs	Client Info		0	0	0
		Oil Age	hrs	Client Info		646	585	517
		Filter Age	hrs	Client Info		61	68	65
		Oil Changed		Client Info		N/A	N/A	N/A
		Filter Changed		Client Info		N/A	N/A	N/A
		Sample Status				NORMAL		NORMAL
WEAR		Iron	ppm	ASTM D5185(m)	>8	0	0	0
		Chromium	ppm	ASTM D5185(m)	>2	0	0	0
		Nickel	ppm	ASTM D5185(m)	>2	0	0	0
		Silver	ppm	ASTM D5185(m)	>2	0	0	0
		Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
		Lead	ppm	ASTM D5185(m)	>3	<1	<1	0
		Copper	ppm	ASTM D5185(m)	>3	<1	0	0
CONTAMINATION		Water		WC Method	>0.1	NEG	NEG	NEG
FLUID CONDITION		Magnesium	ppm	ASTM D5185(m)	0	0	0	0
		Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.43	0.43	0.41
		Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.8		24.3







Laboratory

Sample No. Lab Number : 02631254

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GT57709

Unique Number : 5772407

Received **Tested** 

Diagnosed

: 24 Apr 2024 : 24 Apr 2024

: 24 Apr 2024 - Wes Davis

**Honeywell Engines** 111 S. 34th Street, 301 Receiving, Attn: SOAP Program PHOENIX, AZ

US 85034 Contact: GARRETT

Test Package: G331 (Additional Tests: ICP) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676