

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL


Area


(FJM) PERIMETER AVIATION [53250] [FJM] FAIRCHILD SA227AC P-44722C (S/N AC-696B)

2 Jet Turbine

EASTMAN TURBO OIL 2380 (--- LTR)

					-,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
This is a baseline read-out on the submitted sample.	Sample Number		Client Info		GT57923	GT57416	GT57425
	Sample Date		Client Info		03 May 2024	08 Mar 2024	15 Jan 2024
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		574	489	410
	Filter Age	hrs	Client Info		85	79	82
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185(m)	>8	<1	<1	<1
	Chromium	ppm	ASTM D5185(m)	>2	0	0	0
	Nickel	ppm	ASTM D5185(m)	>2	0	0	0
	Silver	ppm	ASTM D5185(m)	>2	0	0	0
	Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
	Lead	ppm	ASTM D5185(m)	>3	<1	<1	<1
	Copper	ppm	ASTM D5185(m)	>3	0	0	0
CONTAMINATION	Water		WC Method	>0.1	NEG	NEG	NEG
FLUID CONDITION	Magnesium	ppm	ASTM D5185(m)	0	0	0	0
	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.88	0.90	0.89
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.6		









Laboratory Sample No.

: GT57923 Lab Number : 02633985

Received **Tested** Diagnosed Unique Number : 5775138

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 07 May 2024

: 07 May 2024 : 07 May 2024 - Wes Davis

Honeywell Engines 111 S. 34th Street, 301 Receiving, Attn: SOAP Program PHOENIX, AZ

US 85034 Contact: GARRETT

Test Package: G331 (Additional Tests: ICP) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676