## Honeywell

**OIL ANALYSIS REPORT** 


## NORMAL WEAR CONTAMINATION NORMAL **FLUID CONDITION** NORMAL

## Area (CGKPX) SKYCARE AIR AMBULANCE [53364] [CGKPX] FAIRCHILD SA226 P-54155 (S/N TC-264)

Jet Turbine

## ESCO FYYON TURRO OIL 2380 (--- GAL)

ESSO EXXON TURBO OIL 2380 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
This is a baseline read-out on the submitted sample.	Sample Number		Client Info		GT58009	GT57958	GT57819
	Sample Date		Client Info		06 Jun 2024	04 Jun 2024	21 May 2024
	Machine Age	hrs	Client Info		0	0	0
	Oil Age	hrs	Client Info		378	368	313
	Filter Age	hrs	Client Info		9	56	68
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL		NORMAL
WEAR	Iron	ppm	ASTM D5185(m)	>8	0	0	0
	Chromium	ppm	ASTM D5185(m)	>2	0	0	0
	Nickel	ppm	ASTM D5185(m)	>2	0	0	0
	Silver	ppm	ASTM D5185(m)	>2	0	0	0
	Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	<1
	Lead	ppm	ASTM D5185(m)	>3	0	0	0
	Copper	ppm	ASTM D5185(m)	>3	<1	0	0
CONTAMINATION	Water		WC Method	>0.1	NEG	NEG	NEG
FLUID CONDITION	Magnesium	ppm	ASTM D5185(m)	0.0	0	0	0
	Acid Number (AN)	mg KOH/g	ASTM D974*	.38	0.50	0.48	0.47
	Visc @ 40°C	cSt	ASTM D7279(m)	24.1	23.5		24.1



LaboratoryTest Package: G331 (Additional Tests: ICP)To discuss this sample report, contact Customer Service at 1-800-268-2131.Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676

Contact: GARRETT

Contact/Location: GARRETT ? - HONPHO Page 2 of 2