

**OIL ANALYSIS REPORT** 

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL


Area


## (CFIOH) SKYCARE AIR AMBULANCE [53379] [CFIOH] FAIRCHILD SA227-AC P-44345C (S/N AC-432)


Left Jet Turbine


EASTMAN TURBO OIL 2380 (--- GAL)


RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		GT58042	GT57180	GT57170
	Sample Date		Client Info		13 Jun 2024	11 Oct 2023	25 Sep 2023
	Machine Age	hrs	Client Info		0	26229	26161
	Oil Age	hrs	Client Info		35	309	241
	Filter Age	hrs	Client Info		35	68	165
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status					ABNORMAL	
WEAR	Water		WC Method	>0.1	NEG	NEG	NEG
CONTAMINATION	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.67	<u> </u>	<b>△</b> 1.50
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.4	24.9	













CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : GT58042 Lab Number : 02642449 Unique Number : 5799988

Received **Tested** Diagnosed Test Package : G331

: 17 Jun 2024

**Honeywell Engines** 111 S. 34th Street, 301 Receiving, Attn: SOAP Program

PHOENIX, AZ US 85034 Contact: GARRETT

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676