WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**

Machine Id E4-3162

Component Power Take Off

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History
Resample at the next service interval to monitor.	Sample Number		Client Info		WC0933481		
	Sample Date		Client Info		17 Jun 2024		
	Machine Age	kms	Client Info		327		
	Oil Age	kms	Client Info		23		
	Filter Age	kms	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
VEAR	Iron	nnm	ASTM D5185(m)	>200	4		
VEAIT	Chromium	ppm	ASTM D5185(m)		0		
All component wear rates are normal.	Nickel	ppm	ASTM D5185(m)	>10	<1		
	Titanium	ppm	ASTM D5185(m)		0		
	Silver		ASTM D5185(m)		0		
	Aluminum	ppm	ASTM D5185(m)	>50	<1		
	Lead	ppm	ASTM D5185(m)	>50	0		
	Copper	ppm	ASTM D5185(m)	>200	<1		
	Tin	ppm	ASTM D5185(m)		0		
	Vanadium	ppm	ASTM D5185(m)	>10	0		
	White Metal	scalar	Visual*	NONE	NONE		
	Yellow Metal	scalar	Visual*	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185(m)	>50	1		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185(m)	>20	<1		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	Visual*	NONE	NONE		
	Debris	scalar	Visual*	NONE	NONE		
	Sand/Dirt	scalar	Visual*	NONE	NONE		
	Appearance	scalar	Visual*	NORML	NORML		
	Odor	scalar	Visual*	NORML	NORML		
	Emulsified Water	scalar	Visual*	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185(m)	>50	0		
	Boron	ppm	ASTM D5185(m)	200	26		
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185(m)	0	<1		
	Molybdenum	ppm	ASTM D5185(m)	0	0		
	Manganese	ppm	ASTM D5185(m)		<1		
	Magnesium	ppm	ASTM D5185(m)	0	<1		
	Calcium	ppm	ASTM D5185(m)	20	7		
	Phosphorus	ppm	ASTM D5185(m)	1000	345		
	Zinc	ppm	ASTM D5185(m)	20	6		
	Sulfur	ppm	ASTM D5185(m)	22000	21007		
	Acid Number (AN)	mg KOH/g	ASTM D974*		1.02		





CALA ISO 17025:2017 Accredited Laboratory

Laboratory

Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 02643259

: WC0933481 Unique Number : 5800798

Received : 20 Jun 2024 **Tested** Diagnosed

: 20 Jun 2024 : 20 Jun 2024 - Wes Davis

Test Package : MOB 2 (Additional Tests: TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Windsor Spring & Alignment Ltd.

1016 Crawford Ave. Windsor, ON **CA N9A 5C9** Contact: Al Lemay

windsorspring@hotmail.com T: (519)971-8895 F: (519)971-8932