

OIL ANALYSIS REPORT

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL

Area


MIANKI AIRCRAFT REPAIR SERVICE [53399]

DEHAVILLAND DHC3T P-37103C (S/N 287)

Jet Turbine

BP TURBO OIL 2380 (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
This is a baseline read-out on the submitted sample.	Sample Number		Client Info		GT57725	GT57724	GT56906
	Sample Date		Client Info		14 Jun 2024	18 May 2024	07 Jan 2024
	Machine Age	hrs	Client Info		16775	0	0
	Oil Age	hrs	Client Info		20544	25	360
	Filter Age	hrs	Client Info		100	25	68
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185(m)	>8	<1	<1	<1
	Chromium	ppm	ASTM D5185(m)	>2	0	<1	0
	Nickel	ppm	ASTM D5185(m)	>2	0	0	0
	Silver	ppm	ASTM D5185(m)	>2	0	0	0
	Aluminum	ppm	ASTM D5185(m)	>2	<1	<1	1
	Lead	ppm	ASTM D5185(m)	>3	<1	<1	<1
	Copper	ppm	ASTM D5185(m)	>3	<1	<1	<1
CONTAMINATION	Water		WC Method	>0.1	NEG	NEG	NEG
FLUID CONDITION	Magnesium	ppm	ASTM D5185(m)	0	<1	<1	<1
	Acid Number (AN)	mg KOH/g	ASTM D974*	0.43	0.70	0.64	0.77
	Visc @ 40°C	cSt	ASTM D7279(m)	24.2	24.5	24.4	







Laboratory Sample No.

Lab Number : 02643592 Unique Number : 5801131

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 21 Jun 2024 : GT57725

Tested Diagnosed

: 21 Jun 2024

: 21 Jun 2024 - Wes Davis

Honeywell Engines 111 S. 34th Street, 301 Receiving, Attn: SOAP Program PHOENIX, AZ

US 85034 Contact: GARRETT

Test Package: G331 (Additional Tests: ICP) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

T: F: (602)365-2676