



# LIEBHERR

## OIL ANALYSIS REPORT

WEAR	<b>NORMAL</b>
CONTAMINATION	<b>NORMAL</b>
FLUID CONDITION	<b>NORMAL</b>



Area  
**(359465)**  
Machine Id  
**LIEBHERR L556 064990-1757**  
Component  
**Transmission (Manual)**  
Fluid  
**PETRO CANADA DURATRAN (--- GAL)**

### RECOMMENDATION

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>LH0294737</b>	LH0250858	LH0250694
Sample Date		Client Info		<b>11 Jun 2024</b>	11 Jan 2024	26 Jul 2023
Machine Age	hrs	Client Info		<b>11958</b>	9970	8000
Oil Age	hrs	Client Info		<b>0</b>	0	0
Filter Age	hrs	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Changed</b>	Changed	Changed
Filter Changed		Client Info		<b>N/A</b>	N/A	N/A
Sample Status				<b>NORMAL</b>	ABNORMAL	ABNORMAL

### WEAR

All component wear rates are normal.

Iron	ppm	ASTM D5185(m)	>200	<b>4</b>	5	7
Chromium	ppm	ASTM D5185(m)	>5	<b>0</b>	0	0
Nickel	ppm	ASTM D5185(m)	>5	<b>&lt;1</b>	<1	0
Titanium	ppm	ASTM D5185(m)		<b>0</b>	0	0
Silver	ppm	ASTM D5185(m)	>7	<b>&lt;1</b>	0	0
Aluminum	ppm	ASTM D5185(m)	>25	<b>1</b>	1	1
Lead	ppm	ASTM D5185(m)	>45	<b>0</b>	0	0
Copper	ppm	ASTM D5185(m)	>225	<b>1</b>	<1	<1
Tin	ppm	ASTM D5185(m)	>10	<b>0</b>	0	0
Vanadium	ppm	ASTM D5185(m)		<b>0</b>	0	0
White Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE

### CONTAMINATION










There is no indication of any contamination in the fluid.

Silicon	ppm	ASTM D5185(m)	>125	<b>8</b>	7	8
Potassium	ppm	ASTM D5185(m)	>20	<b>15</b>	<1	<1
Water		WC Method	>0.1	<b>NEG</b>	NEG	NEG
Silt	scalar	Visual*	NONE	<b>NONE</b>	VLITE	VLITE
Debris	scalar	Visual*	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	<b>VLITE</b>	NONE	NONE
Appearance	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	Visual*	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	<b>NEG</b>	NEG	NEG

### FLUID CONDITION

The fluid viscosity is lower than typical, possibly indicating the addition of lighter grade fluid. The condition of the fluid is acceptable for the time in service.

Sodium	ppm	ASTM D5185(m)		<b>3</b>	<1	<1
Boron	ppm	ASTM D5185(m)	110	<b>107</b>	97	103
Barium	ppm	ASTM D5185(m)	0.0	<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185(m)	0.0	<b>0</b>	0	<1
Manganese	ppm	ASTM D5185(m)	1	<b>0</b>	0	<1
Magnesium	ppm	ASTM D5185(m)	13	<b>10</b>	12	20
Calcium	ppm	ASTM D5185(m)	3610	<b>3624</b>	3567	3505
Phosphorus	ppm	ASTM D5185(m)	1192	<b>1218</b>	1228	1270
Zinc	ppm	ASTM D5185(m)	1455	<b>1479</b>	1445	1464
Sulfur	ppm	ASTM D5185(m)	2641	<b>3015</b>	3106	2978
Visc @ 40°C	cSt	ASTM D7279(m)	55.14	<b>36.5</b>	▲ 36.2	▲ 36.6



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : LH0294737  
**Lab Number** : 02644628  
**Unique Number** : 5802167  
**Test Package** : MOB 1  
**Received** : 28 Jun 2024  
**Tested** : 28 Jun 2024  
**Diagnosed** : 28 Jun 2024 - Kevin Marson

**Eacom Timber Corporation**  
 100 Old Nairn Centre Road  
 Nairn Centre, ON  
 CA P0M 2L0  
 Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.

T:  
F: