

WEAR
CONTAMINATION
FLUID CONDITION

NORMAL NORMAL

[SOUTH HOLLAND]

## **LIEBHERR LTM 1300 AT1692 - R5 (S/N 071692)**

**Rear Right Final Drive** 

HPL DIFFERENTIAL LIFE 75W90 SYNTHETIC (1 LTR)

HPL DIFFERENTIAL LIFE 75W90 SYNTHETIC (1	LTR)				-,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		HPL010866		
	Sample Date		Client Info		06 Aug 2020		
	Machine Age	mls	Client Info		22832		
	Oil Age	mls	Client Info		7545		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
A/E A D			AOTA DE LOS				
WEAR	Iron	ppm	ASTM D5185m		352		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	3		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	25	0		
	Aluminum	ppm	ASTM D5185m		2		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		15		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	LIGHT		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	2		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water		WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		6		
The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.	Boron	ppm	ASTM D5185m		26		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		5		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		0		
		ppm	ASTM D5185m		436		
	Phosphorus	ppiii					
	Phosphorus Zinc	ppm	ASTM D5185m		14		
			ASTM D5185m ASTM D5185m		14 25056		
	Zinc	ppm					





Certificate L2367

Laboratory Sample No.

Lab Number : 05042980 Unique Number : 9138151 Test Package : MOB 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : HPL010866

Received : 13 Aug 2020 **Tested** : 14 Aug 2020 Diagnosed

: 14 Aug 2020 - Wes Davis

STEVENSON CRANE 410 STEVENSON DR BOLINGBROOK, IL US 60440

Contact: DAVE KOEHNE davidk@stevensoncrane.com T: (630)972-9199

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: