WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL NORMAL


Machine Id


928092-260349


Component Transmission

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number	UOIVI	Client Info	LIIIII/ADII	GFL0102472		
	Sample Date		Client Info		02 Jan 2024		
	Machine Age	hrs	Client Info		23697		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
A/C A D							
WEAR	Iron	ppm	ASTM D5185m		29		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m	. 50	0		
	Aluminum Lead	ppm	ASTM D5185m ASTM D5185m		5 1		
	Copper	ppm	ASTM D5185m				
	Tin	ppm	ASTM D5185m		5 1		
	Vanadium	ppm	ASTM D5185m	>10	0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
			Viouai				
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	13		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	MODER		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		1		
	Boron	ppm	ASTM D5185m		71		
The condition of the fluid is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		1		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m		3		
	Calcium	ppm	ASTM D5185m		131		
	Phosphorus	ppm	ASTM D5185m		214		
	Zinc	ppm	ASTM D5185m		0		
	Sulfur	ppm	ASTM D5185m		1824		
	Visc @ 40°C	cSt	ASTM D445		33.6		











Certificate L2367

Laboratory Sample No. Lab Number

: GFL0102472 : 06055105 Unique Number : 10821054 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 08 Jan 2024 Diagnosed : 10 Jan 2024

Diagnostician : Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 837 - Harrison TS

22820 S State Route 291 Harrisonville, MO

US 64701 Contact: BRYAN SWANSON

bryanswanson@gflenv.com

T:

F: