
WEAR CONTAMINATION **FLUID CONDITION** **ABNORMAL NORMAL NORMAL**

Machine Id **627801**

627801							
Component Diesel Engine							
Fluid							
{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Number		Client Info		IL06073768		
	Sample Date		Client Info		29 Jan 2024		
	Machine Age	mls	Client Info		0		
	Oil Age	mls	Client Info		0		
	Filter Age	mls	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	nnm	ASTM D5185m	< 100	<u> </u>		
Cylinder, crank, or cam shaft wear is indicated.	Chromium	ppm	ASTM D5185m		4		
	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m	74	<1		
	Silver	ppm	ASTM D5185m	>3	0		
	Aluminum	ppm	ASTM D5185m		39		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m	>330	6		
	Tin	ppm	ASTM D5185m	>15	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Ciliaan		ACTM DE10E	05	40		
CONTAMINATION	Silicon Potassium	ppm	ASTM D5185m ASTM D5185m		12 60		
Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.	Fuel	ppm %	ASTM D3163111		<1.0		
	Water	70	WC Method		NEG		
	Glycol		WC Method	70.L	NEG		
	Soot %	%	*ASTM D7844	>3	1.7		
	Nitration	Abs/cm	*ASTM D7624	>20	15.4		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	27.8		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		0		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		21		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		49		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		507		
	Calcium	ppm	ASTM D5185m		1627		
	Phosphorus	ppm	ASTM D5185m		690		
	Zinc	ppm	ASTM D5185m		915		
	Sulfur	ppm	ASTM D5185m		2491		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	29.4		
	Base Number (BN)		ASTM D2896		5.2		
	Visc @ 100°C	cSt	ASTM D445		11.7		







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: IL06073768 : 06073768 : 10855859

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 30 Jan 2024 Diagnosed

: 31 Jan 2024 Diagnostician : Sean Felton

Test Package : FLEET (Additional Tests: FuelDilution) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

IDEALEASE-NORCROSS 4571 NORTH BUFORD HWY NORCROSS, GA US 30071-2808

Contact: RICK MARKS

F: (770)300-0614