
WEAR CONTAMINATION **FLUID CONDITION** **ABNORMAL NORMAL NORMAL**

Machine Id **741001-310090**

Component Transmission (Auto)

PECOMMENDATION Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		GFL0092125	GFL0078017	
	Sample Date		Client Info		24 Jan 2024	29 Mar 2023	
	Machine Age	hrs	Client Info		9409	86438	
	Oil Age	hrs	Client Info		600	0	
	Filter Age	hrs	Client Info		600	0	
	Oil Changed		Client Info		Changed	Not Changd	
	Filter Changed		Client Info		Changed	Not Changd	
	Sample Status				ABNORMAL	NORMAL	
VEAR	Iron	ppm	ASTM D5185m	>160	159	138	
The aluminum level is abnormal. All other component wear rates are normal.	Chromium	ppm	ASTM D5185m		0	<1	
	Nickel	ppm	ASTM D5185m		0	<1	
	Titanium	ppm	ASTM D5185m		0	0	
	Silver	ppm	ASTM D5185m	>5	0	0	
	Aluminum	ppm	ASTM D5185m	>50	△ 64	51	
	Lead	ppm	ASTM D5185m	>50	17	9	
	Copper	ppm	ASTM D5185m	>225	17	15	
	Tin	ppm	ASTM D5185m	>10	2	2	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	12	9	
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	4	2	
	Water		WC Method	>0.1	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		10	9	
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m		54	65	
	Barium	ppm	ASTM D5185m		0	0	
	Molybdenum	ppm	ASTM D5185m		2	3	
	Manganese	ppm	ASTM D5185m		2	3	
	Magnesium	ppm	ASTM D5185m		0	1	
	Calcium	ppm	ASTM D5185m		61	65	
	Phosphorus	ppm	ASTM D5185m		223	245	
	Zinc	ppm	ASTM D5185m		6	8	
	Sulfur	ppm	ASTM D5185m		732	1041	
	Visc @ 40°C	cSt	ASTM D445	34	34.3	34.9	







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10857306

: GFL0092125 : 06075215 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 30 Jan 2024 : 01 Feb 2024 Diagnosed

Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 856 - Houston South

8515 Highway 6 South Houston, TX US 77083

Contact: Apolinar Zacarias pzacariascano@gflenv.com

T: F: