


WEAR CONTAMINATION FLUID CONDITION

NORMAL SEVERE SEVERE

Machine Id

P-4005 Fire Water Pump

| Component Tank Diesel Engine | | | | | | | |
|---|------------------|----------|--------------|---------------|-------------|-------------|-------------|
| DIESEL ENGINE OIL SAE 15W40 (GAL) | | | | | | | |
| RECOMMENDATION | Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
| TESSIMILITERATION | Sample Number | | Client Info | 2 | HLC0003110 | HLC0002666 | HLC0002307 |
| We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. | Sample Date | | Client Info | | 11 Jan 2024 | 05 Oct 2023 | 26 Feb 2023 |
| | Machine Age | hrs | Client Info | | 0 | 0 | 0 |
| | Oil Age | hrs | Client Info | | 0 | 0 | 0 |
| | Filter Age | hrs | Client Info | | 0 | 0 | 0 |
| | Oil Changed | | Client Info | | N/A | N/A | N/A |
| | Filter Changed | | Client Info | | N/A | N/A | N/A |
| | Sample Status | | | | SEVERE | NORMAL | NORMAL |
| WEAR | Iron | ppm | ASTM D5185m | >100 | 4 | 6 | 5 |
| All component wear rates are normal. | Chromium | ppm | ASTM D5185m | >20 | <1 | <1 | <1 |
| | Nickel | ppm | ASTM D5185m | >4 | <1 | 0 | 0 |
| | Titanium | ppm | ASTM D5185m | | <1 | <1 | <1 |
| | Silver | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| | Aluminum | ppm | ASTM D5185m | >20 | 3 | 10 | 2 |
| | Lead | ppm | ASTM D5185m | >40 | 1 | 2 | 1 |
| | Copper | ppm | ASTM D5185m | >330 | <1 | <1 | <1 |
| | Tin | ppm | ASTM D5185m | >15 | 2 | 2 | 1 |
| | Vanadium | ppm | ASTM D5185m | | <1 | 0 | 0 |
| | White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| | Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| CONTAMINATION | Silicon | ppm | ASTM D5185m | >25 | 5 | 5 | 4 |
| CONTAMINATION | Potassium | ppm | ASTM D5185m | | 3 | 3 | 4 |
| There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. | Fuel | % | ASTM D316311 | | 12.1 | <1.0 | <1.0 |
| | Water | 70 | WC Method | | NEG | NEG | NEG |
| | Glycol | | WC Method | 7 0.2 | NEG | NEG | NEG |
| | Soot % | % | *ASTM D7844 | >3 | 0.1 | 0.1 | 0.1 |
| | Nitration | Abs/cm | *ASTM D7624 | >20 | 6.2 | 6.3 | 6.1 |
| | Sulfation | Abs/.1mm | *ASTM D7415 | >30 | 17.9 | 18.5 | 18.7 |
| | Silt | scalar | *Visual | NONE | NONE | NONE | NONE |
| | Debris | scalar | *Visual | NONE | NONE | NONE | NONE |
| | Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| | Appearance | scalar | *Visual | NORML | NORML | NORML | NORML |
| | Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| | Emulsified Water | scalar | *Visual | >0.2 | NEG | NEG | NEG |
| FLUID CONDITION | Sodium | ppm | ASTM D5185m | >158 | 2 | 2 | 2 |
| | Boron | ppm | ASTM D5185m | 250 | 127 | 147 | 130 |
| The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants. | Barium | ppm | ASTM D5185m | 10 | 0 | 0 | 0 |
| | Molybdenum | ppm | ASTM D5185m | 100 | 7 | 9 | 9 |
| | Manganese | ppm | ASTM D5185m | | <1 | <1 | 1 |
| | Magnesium | ppm | ASTM D5185m | | 579 | 661 | 667 |
| | Calcium | ppm | ASTM D5185m | | 1165 | 1317 | 1412 |
| | Phosphorus | ppm | ASTM D5185m | | 960 | 1001 | 997 |
| | Zinc | ppm | | 1350 | 1100 | 1237 | 1248 |
| | Sulfur | ppm | ASTM D5185m | | 3466 | 4011 | 4076 |
| | Oxidation | Abs/.1mm | *ASTM D7414 | | 11.7 | 12.5 | 12.1 |
| | Base Number (BN) | | | | 9.29 | 10.17 | 9.20 |
| | Visc @ 100°C | cSt | ASTM D445 | 14.4 | 9.8 | 13.3 | 13.6 |







Certificate L2367

Laboratory Sample No.

: HLC0003110 Lab Number : 06088357

Unique Number : 10875802

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 13 Feb 2024 **Tested**

: 15 Feb 2024 Diagnosed

Apr12/21

: 15 Feb 2024 - Wes Davis

Test Package: IND 2 (Additional Tests: FuelDilution, PercentFuel)

Contact: SEAN LOWTHER slowther@hilcorp.com T: (907)659-6800

604 WAREHOUSE ENDICOTT

PRUDHOE BAY, AK

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F:

HILCORP ALASKA LLC - ENDICOTT

US 99734