

## **VOLVO L90H 625035**

Front Axle

DIESEL ENGINE OIL SAE 15W40 ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP444261	VCP395993	
	Sample Date		Client Info		15 Feb 2024	30 Jan 2023	
	Machine Age	hrs	Client Info		3984	3010	
	Oil Age	hrs	Client Info		0	1000	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Not Changd	
	Filter Changed		Client Info		N/A	Not Changd	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185m	>300	78	64	
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	2	2	
	Nickel	ppm	ASTM D5185m	>4	0	<1	
	Titanium	ppm	ASTM D5185m		0	<1	
	Silver	ppm	ASTM D5185m		0	3	
	Aluminum	ppm	ASTM D5185m	>15	1	<1	
	Lead	ppm	ASTM D5185m	>4	1	1	
	Copper	ppm	ASTM D5185m	>200	0	<1	
	Tin	ppm	ASTM D5185m	>15	<1	<1	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	LIGHT	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	20	21	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	<1	0	
There is no indication of any contamination in the oil.	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m	>158	4	3	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	250	121	138	
·	Barium	ppm	ASTM D5185m	10	0	0	
	Molybdenum	ppm	ASTM D5185m	100	3	4	
	Manganese	ppm	ASTM D5185m		5	5	
	Magnesium	ppm	ASTM D5185m		11	19	
	Calcium	ppm	ASTM D5185m		3516	3969	
	Phosphorus	ppm	ASTM D5185m		1195	1172	
	Zinc	ppm	ASTM D5185m		1338	1527	
	Sulfur	ppm	ASTM D5185m		4218	5036	
	Visc @ 40°C	cSt	ASTM D445	115	47.2	47.7	





Certificate L2367

Laboratory Sample No.

: VCP444261 Lab Number : 06102603 Unique Number : 10900833 Test Package : MOBCE

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Feb 2024 **Tested** : 28 Feb 2024

: 29 Feb 2024 - Don Baldridge Diagnosed

**RIPA AND ASSOCIATES** 10149 FISHER AVENUE TAMPA, FL US 33619

Contact: PM Services PMServices@ripaconstruction.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: RIPTAM [WUSCAR] 06102603 (Generated: 02/29/2024 20:40:57) Rev: 1

Contact/Location: PM Services ? - RIPTAM