
**WEAR CONTAMINATION FLUID CONDITION**  **ATTENTION ABNORMAL NORMAL** 

## Area [661614 RYAN GOLF] **VOLVO A40G 352296**

Component Transmission (Auto)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
We advise that you check all areas where dirt can enter the system. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP454104		
	Sample Date		Client Info		30 Jan 2024		
	Machine Age	hrs	Client Info		1202		
	Oil Age	hrs	Client Info		1202		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	43		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		3		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>50	<u> </u>		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>225	22		
	Tin	ppm	ASTM D5185m	>10	3		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	nnm	ASTM D5185m	>20	<u>^</u> 20		
	Potassium	ppm	ASTM D5185m		4		
Elemental levels of silicon (Si) and aluminum (Al) indicate alumina- silicate (coarse dirt) ingress.	Water	ppm	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium		ASTM D5185m				
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m	107	6 78		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		ں <1		
	Manganese	ppm	ASTM D5185m		6		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		104		
	Phosphorus	ppm	ASTM D5185m		204		
	Zinc	ppm	ASTM D5185m		6		
	Sulfur	ppm		1336	2266		
	Visc @ 40°C	cSt	ASTM D445		27.9		





Certificate L2367

Laboratory Sample No.

: VCP454104 Lab Number : 06103399 Unique Number: 10901629 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 28 Feb 2024

: 29 Feb 2024 **Tested** : 01 Mar 2024 - Sean Felton Diagnosed

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619

Contact: JOHN FARDELLA john.fardella@altg.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (813)630-0077 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (813)630-2233