WEAR CONTAMINATION FLUID CONDITION

NORMAL

ABNORMAL


NORMAL


Machine Id


E-ONE LADDER 53


Component
Hvdraulic System

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number	JOIVI	Client Info	Entity/NOT	WC0917776		
We recommend you service the filters on this component. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Date		Client Info		05 Apr 2024		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
VEAR	Iron	ppm	ASTM D5185m	>20	<1		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>10	0		
	Lead	ppm	ASTM D5185m	>10	<1		
	Copper	ppm	ASTM D5185m	>75	2		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	<1		
There is a moderate amount of visible silt present in the sample.	Potassium	ppm	ASTM D5185m	>20	0		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	▲ MODER		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		0		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		53		
	Calcium	ppm	ASTM D5185m		49		
	Phosphorus	ppm	ASTM D5185m		328		
	Zinc	ppm	ASTM D5185m		374		
	Sulfur		ASTM D5185m		1252		











Certificate L2367

Laboratory Sample No.

Lab Number : 06155417 Unique Number : 10990840 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0917776 Received : 19 Apr 2024 **Tested** : 22 Apr 2024

Diagnosed

: 24 Apr 2024 - Don Baldridge

GRINNELL, IA US 50112 Contact: DON SICARD

GRINNELL FIRE DEPT

1020 SPRING ST

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (641)236-2688 F: