
WEAR CONTAMINATION **FLUID CONDITION** **ABNORMAL** NORMAL **NORMAL**

Machine Id

KUBOTA SVL97-2 MTL-11

Left Final Drive

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.	Sample Number		Client Info		CL0005369		
	Sample Date		Client Info		18 Apr 2024		
	Machine Age	hrs	Client Info		1212		
	Oil Age	hrs	Client Info		1212		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	△ 956		
Gear wear is indicated.	Chromium	ppm	ASTM D5185m		<u> 15</u>		
	Nickel	ppm	ASTM D5185m		3		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>25	2		
	Lead	ppm	ASTM D5185m	>25	1		
	Copper	ppm	ASTM D5185m	>50	3		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	21		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	4		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	150	0		
	Barium	ppm	ASTM D5185m		13		
	Molybdenum	ppm	ASTM D5185m		2		
	Manganese	ppm	ASTM D5185m		14		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		74		
	Phosphorus	ppm		2000	272		
	Zinc	ppm	ASTM D5185m		70		
	Sulfur	ppm	ASTM D5185m	20000	23229		
	Visc @ 40°C	cSt	ASTM D445	140	173		







Certificate L2367

Laboratory Sample No.

: CL0005369 Lab Number : 06159904 Unique Number: 10995327 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Apr 2024

Tested : 25 Apr 2024 Diagnosed : 26 Apr 2024 - Sean Felton **BULLSEYE CONSTRUCTION**

581 N POLK ST PINEVILLE, NC US 28134

Contact: SERVICE MANAGER

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: