
WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL **NORMAL**


Machine Id


BELL UH-1H N911KP Component Hydraulic System Fluid

{not provided} (QTS)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.	Sample Number		Client Info		GF0001486		
	Sample Date		Client Info		29 Mar 2024		
	TSN	hrs	Client Info		0		
	TSO	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>20	0		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>10	<1		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>10	2		
	Lead	ppm	ASTM D5185m	>20	<1		
	Copper	ppm		>20	<1		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>15	10		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	0		
	Water		WC Method	>0.05	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.05	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		0		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		44		
	Phosphorus	ppm	ASTM D5185m		723		
	Zinc	ppm	ASTM D5185m		13		
	Sulfur	ppm	ASTM D5185m		4		
	Visc @ 40°C	cSt	ASTM D445		15.3		











Certificate L2367

Laboratory Sample No.

: GF0001486 Lab Number : 06159967 Unique Number : 10995390 Test Package : AVI 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 24 Apr 2024 **Tested** : 25 Apr 2024

Diagnosed : 26 Apr 2024 - Don Baldridge

67 D STREET FILMORE, CA US 93015 Contact: PHIL DIFIORE

ROTORCRAFT SUPPORT INC

phil@rotorcraftsupport.com T: (818)997-7667 F: (818)997-1513

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.